



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 01/11/2024        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 01/11/2024        |                     | Kempton Park - GT        |

Vehicle Data

|                 |  |                         |              |
|-----------------|--|-------------------------|--------------|
| Vehicle Type    | LIGHT LOAD VEHICLE   | Registered Owner        |              |
| Manufacturer    | VOLKSWAGEN   | Registration Number     | HNJ863FS     |
| Model           | AMAROK 2.0 BITDI D-CAB 4MOTION<br>HIGHLINE 132KW DSL PU AT [2012-2014] | Register Number         |              |
| VIN             | WV1ZZZ2HZDA064136  | Date Of First Licensing |              |
| Engine Number   |  | Last COR                |              |
| Doors           | 4  | License Expiry Date     | 31/10/2021   |
| Color           | SILVER   | Power / Displacement    |              |
| Year Model      | 2013   | Paint Finish            | M - METALLIC |
| Km Reading      | 142,161 KM   | Fuel                    | DIESEL       |
| Cab / Body Type | DOUBLE CAB   | Transmission            | AUTOMATIC    |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

| Damage                                   | Repair Way                        |
|--|-----------------------------------|
| Center Console / Cubbyhole + Lid Damaged | Repair                            |
| Front Bumper Paintwork • Scratched       | Repair                            |
| Front Fender Left Paintwork • Scratched  | Repair                            |
| Front Fender Right Paintwork • Scratched | Repair                            |
| Rear Fender Left Paintwork • Scratched   | Repair                            |
| Rear Fender Right Paintwork • Scratched  | Repair                            |
| Door Front Left Paintwork • Scratched    | Repair                            |
| Door Front Right Paintwork • Scratched   | Repair                            |
| Door Rear Left Paintwork • Scratched     | Repair                            |
| Door Rear Right Dented                   | Repair                            |
| Tailgate Paintwork • Scratched           | Repair                            |
| Caliper 1. Axle left Leak                | Repair                            |
| Caliper 1. Axle right Leak               | Repair                            |
| Brake Drum 2. Axle left Defective        | Repair                            |
| Brake Drum 2. Axle right Defective       | Repair                            |
| Aircon malfunction                       | Repair                            |
| Brakes                                   | No brake test done vehicle is 4wd |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

1 / 10



## CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

### Brakes

#### Brake Test Results

No Brake Test on a brake test machine has been performed.

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                                  |
| Front               | -                  | -                  | -                |                                  |
| Rear                | -                  | -                  | -                |                                  |
| Emergency / Parking | -                  | -                  | -                |                                  |

### Tyres and Rims

#### Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model    | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|----------|-------|-----------------|------------------|
| Front Left  | 255/60R18 | 112T             | Pirelli     | Scorpion | V     | 4316            | 2 mm             |
| Front Right | 255/60R18 | 112T             | Pirelli     | Scorpion | V     | 3216            | 2 mm             |
| Rear Left   | 255/60R18 | 112T             | Bridgestone | Dueler   | V     | 1613            | 3 mm             |
| Rear Right  | 255/60R18 | 112T             | Pirelli     | Scorpion | V     | 2017            | 2 mm             |
| Spare       | 255/60R18 | 112T             | Pirelli     | Scorpion | V     | 3316            | 2 mm             |

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                | Code    | Description   | Status |
|----|-----------------------|---------|---|--------|
| 1  | ENGINE CONTROL MODULE | P068A00 | ECM/PCM POWER RELAY DE-ENERGIZED PERFORMANCE -TOO EARLY |        |

### Inspection Conditions

No Test Drive  
 Battery Flat  
 Engine number – not possible to verify engine number (not visible without dismantling)  
 Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Vehicle got minor scratches, stone chips and dents.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Andrick Wymers

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016595023


DATE  
01/11/2024




Shock report




Diagnostic report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

3 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

4 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024




INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

5 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

6 / 10



CONDITION REPORT

Report No: 2016595023


DATE  
01/11/2024



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

7 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

8 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WV1ZZZ2HZDA064136

10 / 10



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024



Expection bottle




Oil cap and dipstick



Water level



Center Console / Cubbyhole + Lid



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016595023


DATE  
01/11/2024




Door Front Right



Front Fender Right




Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024



Door Rear Left



Rear Fender Left



Tailgate



Brake Drum 2. Axle left



Brake Drum 2. Axle right



Caliper 1. Axle right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016595023

DATE  
01/11/2024

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



Caliper 1. Axle left



**CONDITION REPORT**

**Report No: 2016595023**

**DATE**  
**01/11/2024**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za