



CONDITION REPORT



Report No:
2017305918
DATE
01/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	01/10/2026		M57 Pretoria Road - 1619
Inspection Date	01/10/2026		Kempton Park -

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LBS172NW
Model	AMAROK 2.0 BITDI D-CAB HIGHLINE DSL PU AT [2015-2017]	Register Number	
		Date Of First Licensing	
VIN	WV1ZZZ2HZGA055787	Last COR	
Engine Number		License Expiry Date	31/05/2026
Doors	4	Power / Displacement	
Color	SILVER	Paint Finish	M - METALLIC
Year Model	2016	Fuel	DIESEL
Km Reading	173,893 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:

2017305918

DATE

01/10/2026



Damage

Repair Way

Bonnet stay and shocks Defective	Repair
Windscreen Wiper Missing	Replace
Tail Light Right Damaged	Replace
Seat Front Right Torn / Cut	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Rear bumper Dented	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Spare Tyre Damaged	Replace
Sunglasses Holder damage	Repair
Airbag warning light illuminated	Repair
Engine management light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	5.6	5.6	-	
Rear	3.4	2.5	-	
Emergency / Parking	2.2	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/60R18	112H	General	Grabber	V	3821	2 mm
Front Right	255/60R18	112H	General	Grabber	V	3921	3 mm
Rear Left	255/60R18	112H	General	Grabber	V	0724	5 mm
Rear Right	255/60R18	112T	Continental	Contact	V	5015	3 mm
Spare	255/60R18	112H	General	Grabber	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:
2017305918
DATE
01/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	P056200	SYSTEM VOLTAGE LOW VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. BODY EXTERIOR - SIGNS OF SPRAY WORK DONE ON SOME BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:

2017305918

DATE

01/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:
2017305918
DATE
01/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:

2017305918

DATE

01/10/2026



ENGINE 1



ENGINE 2



CHASSIS



Expenditure bottle



Oil cap and dipstick



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:
2017305918
DATE
01/10/2026



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Spare wheel

[illegible]

Shock and brake report

[illegible]

Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WV1ZZZ2HZGA055787




CONDITION REPORT




Report No:
2017305918
DATE
01/10/2026




Diagnostic Report page 2



Diagnostic Report page 3



Diagnostic Report page 4



Seat Front Right



Water level



Bonnet stay and shocks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT




Report No:
2017305918
DATE
01/10/2026



Windscreen Wiper



Tail Light Right



Door Rear Right



Door Front Right



Rear Fender Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:
2017305918
DATE
01/10/2026



Front Bumper



Front Fender Left



Front Bumper



Side Mirror Right



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787



CONDITION REPORT



Report No:

2017305918

DATE

01/10/2026



Rear Fender Left



Rear bumper



Rear bumper

VIN	WV1ZZZ2HZGA055787	Model	VW Amarok
Test date	11/33	VIN	WV1ZZZ2HZGA055787
Test results			
Side-slip test			
Front axle	-16 m/s	Rear axle	-3 m/s
Shock absorber test (MSD1000)			
Front axle	left	right	Difference
	0.14	0.08	43 %
Rear axle	0.18	0.05	17 %
Total weight			2499 kg
Brake test			
Brake force			
Front axle	left	right	Difference
	5.68 kN	5.68 kN	0 %
Parking brake	3.29 kN	1.38 kN	44 %
Rear axle	3.45 kN	3.50 kN	2 %
Final evaluation static			
Deceleration service brake		21 %	
Deceleration parking brake		15 %	
Total weight			2499 kg

Parking Brake Performance



Spare Tyre

DEKRA Automotive (PTY) Ltd.

97 Willem Cruywagen Ave

Klerksoord, Pretoria, 0200

Phone: 012 542 4867

www.dekraauto.co.za

VIN: WV1ZZZ2HZGA055787