



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	23/09/2026		M57 Pretoria Road - 1619
Inspection Date	23/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	FVY755L
Model	AMAROK 3.0 TDI D-CAB 4MOTION HIGHLINE PLUS 190KW DSL PU AT [2021-2023]	Register Number	
		Date Of First Licensing	
VIN	WV1ZZZ2HZNA030546	Last COR	
Engine Number		License Expiry Date	30/11/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2022	Fuel	DIESEL
Km Reading	136,844 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:

2017301980

DATE

23/09/2026



Damage

Repair Way

Fuel Gauge Defective	Repair
Engine Management Lights Set	Repair
Tail Light Left Damaged	Repair
Tail Light Right Damaged	Repair
Fog Light Front Left Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Tailgate Damaged	Repair
Windscreen Damaged	Replace
Engine to silencer pipe Welded	Replace
Fuel Tank Leak	Repair
Brakes Insufficient	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	114T	Hankook	Right	V	3325	3 mm
Front Right	265/60R18	114T	Hankook	Radial	V	3325	3 mm
Rear Left	265/60R18	114T	Hankook	Radial	V	1422	3 mm
Rear Right	265/60R18	114T	Hankook	Radial	V	3625	3 mm
Spare	265/60R18	114T	Hankook	Radial	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE 1	U350100	CONTROL MODULE INPUT POWER A CIRCUIT LOW	

Inspection Conditions

No undercarriage inspection
No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 8 DTC'S AT TIME OF TESTING SEE DTC REPORT. Electrical Components and Instruments: Central locking malfunctioning driver side door does not unlock with key fob. After opening door from the inside driver side door opens correctly from the outside. vehicle electronics malfunctioning.

Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WV1ZZZ2HZNA030546




CONDITION REPORT




Report No:
2017301980
DATE
23/09/2026



Brake test.




Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



Front Bumper



Front Bumper



Grill



Fog Light Front Left



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



Door Rear Left



Rear Fender Left



Tailgate



Rear Fender Right



Front Fender Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546



CONDITION REPORT



Report No:
2017301980
DATE
23/09/2026



Windscreen



Tail Light Left



Tail Light Right



Engine Management Lights



Fuel Gauge



Fuel Tank

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546

**CONDITION REPORT**

Report No:
2017301980
DATE
23/09/2026



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WV1ZZZ2HZNA030546