



CONDITION REPORT



Report No:
2016941265
DATE
10/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/07/2025		M57 Pretoria Road - 1619
Inspection Date	10/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	JZ43KKGP
Model	TIGUAN ALLSPACE 1.4 TSI TRENDLINE 110KW DSG [2018-2019]	Register Number	
		Date Of First Licensing	
VIN	WVGZZZ5NZJM210570	Last COR	
Engine Number		License Expiry Date	30/04/2024
Doors	5	Power / Displacement	
Color	GREEN	Paint Finish	M - METALLIC
Year Model	2018	Fuel	PETROL
Km Reading	241,098 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		


Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZJM210570



Damage	Repair Way
Tail Light Left Damaged	Replace
Seat Front Right Torn / Cut	Repair
Seat Rear (2. Row) Damaged	Repair
Number Plate Rear Missing	Replace
Front Bumper Residual Traces of Repair	Repair
Bonnet Residual Traces of Repair	Repair
Bonnet slam plate (Shock tower/ Inner tray) Welded	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Rear Fender Left / Inner Tray Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Residual Traces of Repair	Repair
Windscreen Cracked	Replace
Service Brake Performance Rear Axle Malfunction	Repair
Parking Brake Performance Malfunction	Repair
Stabilizer Mounting Rear Left Damaged	Replace
Tyre Front Right Smooth	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Gearbox Mountings Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Engine Noise Excessive	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Signs of poor repair work done on some body panels
Body exterior	Signs of spray work done on some body panels
Gear box malfunction	Repair
Electronics malfunction	Repair
Body exterior	Discoloring on some body panels
Engine management lights illuminated	Repair
Parking brake button malfunction	Repair
Signs of oil leak bottom of engine covered	Repair
Front tyres size differs	Replace



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.5	4.0	-	
Rear	0.0	0.0	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/65R17	99V	Continental	Contact	V	1421	2 mm
Front Right	215/65R17	99V	Bridgestone	Dueler	V	1617	0 mm
Rear Left	215/65R17	104T	Hankook	Ventus	V	0520	3 mm
Rear Right	225/65R17	102H	Goodyear	Efficient gr	V	3719	3 mm
Spare	T145/85R18	103M	Ling long	Temporary	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE/ STATIC	B10051B	DRIVER HEAD CURTAIN AIRBAG IGNITER RESISTANCE TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZJM210570



Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570

Test results

Item	Result	Remarks
Shock absorbers	Good	
Brake pads	Good	
Brake discs	Good	
Steering rack	Good	
Ball joints	Good	
CV axles	Good	
Wheels	Good	
Tires	Good	
Oil level	Good	
Water level	Good	
Brake fluid	Good	
Power steering fluid	Good	
Windshield wipers	Good	
Headlights	Good	
Brake lights	Good	
Turn signals	Good	
Horn	Good	
Seatbelts	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	

Shock and brake report

Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570

Test results

Item	Result	Remarks
Engine	Good	
Transmission	Good	
Drivetrain	Good	
Brake system	Good	
Steering system	Good	
Suspension system	Good	
Wheels and tires	Good	
Fluid levels	Good	
Electrical system	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	

Diagnostic report

Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570

Test results

Item	Result	Remarks
Engine	Good	
Transmission	Good	
Drivetrain	Good	
Brake system	Good	
Steering system	Good	
Suspension system	Good	
Wheels and tires	Good	
Fluid levels	Good	
Electrical system	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	

Diagnostic report

Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570

Test results

Item	Result	Remarks
Engine	Good	
Transmission	Good	
Drivetrain	Good	
Brake system	Good	
Steering system	Good	
Suspension system	Good	
Wheels and tires	Good	
Fluid levels	Good	
Electrical system	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	

Diagnostic report

Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570

Test results

Item	Result	Remarks
Engine	Good	
Transmission	Good	
Drivetrain	Good	
Brake system	Good	
Steering system	Good	
Suspension system	Good	
Wheels and tires	Good	
Fluid levels	Good	
Electrical system	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	


Diagnostic report

Vehicle: 2016 MAZDA3
Engine: 2.5L 4-cyl
Transmission: 6-speed manual
Mileage: 125,000 km
VIN: WVGZZZ5NZJM210570


Test results

Item	Result	Remarks
Engine	Good	
Transmission	Good	
Drivetrain	Good	
Brake system	Good	
Steering system	Good	
Suspension system	Good	
Wheels and tires	Good	
Fluid levels	Good	
Electrical system	Good	
Interior	Good	
Exterior	Good	
Overall condition	Good	


Diagnostic report



Diagnostic report




Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



Expenditure bottle



CHASSIS



Oil cap and dipstick

Test results	
Side-slip test	Front axle: -4 m/s
Shock absorber test (MSD3000)	Front axle: left 0.23, right 0.26, Difference 7 %; Rear axle: left 0.23, right 0.23, Difference 0 %
Parking brake	Front axle: left 3.54 kN, right 4.07 kN, Difference 13 %; Rear axle: left 8.21 kN, right 8.21 kN, Difference 0 %
Brake test	Front axle: left 3.54 kN, right 4.07 kN, Difference 13 %; Rear axle: left 8.21 kN, right 8.21 kN, Difference 0 %
Lockdown service brake	Front axle: left 8.21 kN, right 8.21 kN, Difference 0 %; Rear axle: left 8.21 kN, right 8.21 kN, Difference 0 %
Lockdown parking brake	Front axle: left 8.21 kN, right 8.21 kN, Difference 0 %; Rear axle: left 8.21 kN, right 8.21 kN, Difference 0 %
Total weight	905 kg

Parking Brake Performance

Side-slip test	
Front axle	-4 m/s
Shock absorber test	
Front axle	left 0.23, right 0.26, Difference 7 %
Rear axle	left 0.23, right 0.23, Difference 0 %
Brake test	
Front axle	left 3.54 kN, right 4.07 kN, Difference 13 %
Rear axle	left 8.21 kN, right 8.21 kN, Difference 0 %
Lockdown service brake	
Front axle	left 8.21 kN, right 8.21 kN, Difference 0 %
Rear axle	left 8.21 kN, right 8.21 kN, Difference 0 %
Lockdown parking brake	
Front axle	left 8.21 kN, right 8.21 kN, Difference 0 %
Rear axle	left 8.21 kN, right 8.21 kN, Difference 0 %
Total weight	905 kg

Service Brake Performance Rear Axle



Water level



Bonnet



Windscreen



Seat Front Right



Seat Rear (2. Row)



Seat Rear (2. Row)



Number Plate Rear



Tail Light Left



A • Pillar Right



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



A • Pillar Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear Fender Left / Inner Tray



Rear Fender Left / Inner Tray



Boot Lid / Hatch door



Rear bumper



Rear bumper



Stabilizer Mounting Rear Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox Mountings



Tyre Front Right



Bolt(s) / Nut(s) Front Wheel Right



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left



Bolt(s) / Nut(s) Rear Wheel Right



Bonnet slam plate (Shock tower/ Inner tray)



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZJM210570