



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/07/2025		M57 Pretoria Road - 1619
Inspection Date	29/07/2025		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	JZ71XJGP
Model	POLO SEDAN 1.6 COMFORTLINE [2019-2021]	Register Number	
VIN	WVWZZZ60ZKT096366	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/05/2025
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT METALLIC
Km Reading	145,638 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVWZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Damage	Repair Way
Radiator Water Leak	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Air Suspension Front Left Defective	Replace
Air Suspension Front Right Defective	Replace
Air Suspension Rear Left Defective	Replace
Air Suspension Rear Right Defective	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Main Beam Right Damaged	Replace
Radiator Cradle Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.51	2.48	-	
Rear	2.46	2.74	-	
Emergency / Parking	1.88	2.05	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/35R17	82V	Acceiera	Radial	V	3024	4 mm
Front Right	185/35R17	74V	Hockenheim	Radial	V	1524	4 mm
Rear Left	185/35R17	74V	Hockenheim	Radial	V	1624	4 mm
Rear Right	185/35R17	74W	Hockenheim	Radial	V	1624	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ELECTRONIC CENTRAL ELECTRIC	03156:004	ANTI- THEFT ALARM SYSTEM SENSOR-NO SIGNAL /COMMUNICATION	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels. non-standard sunroof fitted to vehicle.

Axle and Suspension: non-standard air suspension fitted to Vehicle. left rear air suspension does not hold pressure.

Undercarriage: Vehicle is a cut and join. vehicle is unsafety drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WVVZZZ60ZKT096366



CONDITION REPORT




Report No:
2016961407
DATE
29/07/2025




Oil cap and dipstick.




non-stander air suspension.




Brake test.



Diagnostic.



Diagnostic.



Undercarriage front.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVVZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Manual.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage rear.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WWWZZZ60ZKT096366




CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Front Fender Right



Rear Fender Right



Roof



Boot Lid / Hatch door



Air Suspension Rear Left



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VWWZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Control Arm Bush(es) Front Axle Left



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right



Main Beam Right



Radiator Cradle



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVVZZZ60ZKT096366



CONDITION REPORT



Report No:
2016961407
DATE
29/07/2025



Air Suspension Front Left



Air Suspension Front Right



Air Suspension Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVVZZZ60ZKT096366