Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023153206
Test Time: 2026-10-23 15:32:06
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZMU020001

Odometer Reading: 120603
License Plate: MD82BZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	0
09 - Electronic central electric	4
15 - Airbag	4
17 - Instrument cluster	1
19 - Gateway	1
25 - Immobilizer	1
44 - Power steering	2
56 - Radio	4
61 - Battery Regulation	0

DTC (17)

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic
01504:010	License plate lamp - Open circuit/short circuit to B+	Active/static

15 - Airbag (4 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B10061B	Driver seat belt tensioner igniter ,Resistance too high	Active/static

B10071B	Front passenger side seat belt tensioner igniter , Resistance too high	Active/static
U140000	Function restriction ,due to low voltage	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 ,Open circuit	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

56 - Radio (4 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00856:011	Antenna, on radio - Open circuit	Passive/Sporadic
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2017316616

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.