Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261012153518
Test Time: 2026-10-12 15:35:18
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZPU005844

Odometer Reading: 313679
License Plate: LB10JVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	15
03 - Brakes 1	5
04 - Steering Angle Sender	0
08 - Air conditioning	0
09 - Electronic central electric	5
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	1
25 - Immobilizer	0
44 - Power steering	1
56 - Radio	1
61 - Battery Regulation	0

DTC (28)

01 - Engine Control Module 1 (15 DTCs)

DTC	Description	Status
P15AA00	Engine oil pressure ,Below lower limit	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Active/static
P035100	Ignition Coil A Primary/secondary Circuit	Passive/Sporadic
P029900	Turbocharger/supercharger underboost	Active/static
U101700	ABS Control Module ,Check event memory	Active/static
P070400	Clutch switch input circuit	Passive/Sporadic

P034100	Camshaft Position Sensor ,Implausible signal	Passive/Sporadic
P036600	Camshaft position sensor exhaust bank 1 ,Implausible signal	Passive/Sporadic
P001700	Camshaft position 2/crankshaft position sensor (bank 1) , Incorrect allocation	Passive/Sporadic
P030000	Random Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
P055600	Brake booster pressure sensor circuit range/performance	Passive/Sporadic
P044100	EVAP Emission Contr.Sys.Incorrect ,Purge Flow	Active/static

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C102D00	Tire pressure warning	Active/static
C114602	TPMS ,Signal error	Active/static
C101B01	Right front ABS Wheel Speed Sensor (WSS) ,Electrical fault	Active/static
C101B29	Right front Wheel Speed Sensor (WSS) Range/performance	Active/static

09 - Electronic central electric (5 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00901:010	Bulbs for back-up light - Open circuit/short circuit to B+	Active/static
01800:008	Light switch - Implausible signal	Passive/Sporadic
00979:010	Right low beam headlamp bulb - Open circuit/short circuit to B+	Active/static
01504:010	License plate lamp - Open circuit/short circuit to B+	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U111300	Function limitation due to received malfunction value	Active/static

56 - Radio (1 DTC)

DTC	Description	Status

00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

Technician Notes
2017310967

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.