# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAWZMU079518

Odometer Reading: 187775km
License Plate: KV36ZZGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 16 )

| System | Status/DTC |
|---|---|
| 01 - Engine Control Module 1 | 3 |
| 02 - Transmission electronics | 0 |
| 03 - Brakes 1 | 1 |
| 08 - Air conditioning | 0 |
| 09 - Electronic central electric | 4 |
| 15 - Airbag | 0 |
| 17 - Instrument cluster | 4 |
| 19 - Gateway | 0 |
| 44 - Power steering | 2 |
| 55 - Headlamp range control | 0 |
| 5F - Information electronics 1 | 0 |
| 76 - Parking aid | 0 |
| A9 - Structure-Borne Sound Actuator | 1 |
| CA - Sunroof control module | 2 |
| D6 - Light control left 2 | 0 |
| D7 - Light control right 2 | 0 |

## DTC ( 17 )

### 01 - Engine Control Module 1 ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|
| P310B00 | Fuel low pressure regulation<br>Fuel pressure out of range | Passive/Sporadic |

| | | |
|---|---|---|
| P017200 | Fuel Trim,Bank1<br>System too Rich | Passive/Sporadic |
| P218800 | System too rich at idle, Bank 1 | Passive/Sporadic |

## 03 - Brakes 1 ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| C102D00 | Tire pressure warning | Passive/Sporadic |

## 09 - Electronic central electric ( 4 DTCs )

| DTC | Description | Status |
|---|---|---|
| B121F15 | Left fog lamp bulb<br>Circuit open or short to positive | Passive/Sporadic |
| B122015 | Right fog lamp bulb<br>Circuit open or short to positive | Passive/Sporadic |
| B147A18 | Remote control vehicle key 2<br>Insufficient current | Passive/Sporadic |
| B132329 | Driver side rear power window button<br>Range/performance | Active/static |

## 17 - Instrument cluster ( 4 DTCs )

| DTC | Description | Status |
|---|---|---|
| U111000 | Function restriction due to communication interruption | Passive/Sporadic |
| B104B31 | Key<br>No signal | Passive/Sporadic |
| B104C29 | Key<br>Range/performance | Passive/Sporadic |
| U112100 | Data bus message missing | Passive/Sporadic |

## 44 - Power steering ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| U112100 | Data bus message missing | Passive/Sporadic |
| B200FF0 | Internal malfunction | Passive/Sporadic |

## A9 - Structure-Borne Sound Actuator ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| U112100 | Data bus message missing | Passive/Sporadic |

## CA - Sunroof control module ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| B157429 | Button for sliding roof<br>Range/performance | Passive/Sporadic |
| B13C429 | Sunroof button<br>Range/performance | Passive/Sporadic |

# Technician Notes
2017307088

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*