Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVTFS40JMD127410

Odometer Reading: 81303
License Plate: LH20LJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.70

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (15)

System		Status/DTC
ECM(Engine Control Module)		0
ABS(Anti-lock Brake System)		8
SRS(Supplemental Restraint System)		0
IBS(Intelligent Battery System)		0
AT(Automatic Transmission)		0
TCCM(Transfer Case Control Module)		0
PAS(Parking Aid System)	ADAS	9
SRR_RL(Short Range Radar (Left Rear))	ADAS	0
SRR_RR(Short Range Radar (Right Rear))	ADAS	0
BCM(Body Control Module)		8
CGW(Central Gateway)		0
HVAC(Heating Ventilation and Air Conditioning)		1
HLAL(Head Lamp Auto Leveling)	ADAS	1
WAM(Wireless Access Module)		0
NCU(Navigation Center Unit)		0

DTC (27)

ABS(Anti-lock Brake System) (8 DTCs)

DTC	Description	Status
C0020_01	Pump motor electrical fault	Not present
C052E_49	Valve relay internal circuit fault	Not present
U0100_87	Lost communication with ECM	Not present

U0101_87	Lost communication with TCM	Not present
U0102_87	Lost communication with Transfer Case Control Module (TCCM)	Not present
U0136_87	Lost communication with DLC	Not present
U0140_87	Lost communication with BCM	Not present
U0155_87	Lost communication with meter	Not present

PAS(Parking Aid System) (9 DTCs)

DTC	Description	Status
C1117_13	Parking aid rear sensor internal supply circuit open	Not present
C1118_01	Parking aid right rear outer sonar sensor communication impossible	Not present
C1119_01	Parking aid left rear outer sonar sensor communication impossible	Not present
C111A_01	Parking aid right rear inner sonar sensor communication impossible	Not present
C111B_01	Parking aid left rear inner sonar sensor communication impossible	Not present
U0100_00	Lost communication with ECM or PCM	Not present
U0101_00	Lost communication with TCM	Not present
U0140_00	Lost Communication with BCM	Not present
U0155_00	Lost communication with instrument panel cluster (IPC) control module	Not present

BCM(Body Control Module) (8 DTCs)

DTC	Description	Status
C1725_13	Left rear turn signal lamp output circuit open	Not present
C1724_13	Right rear turn signal lamp output circuit open	Not present
C1707_13	Backup lamp circuit open	Not present
B1706_98	Front wiper output circuit component or system overtemperature	Not present
U1800_86	Lost communication with ECM	Not present
U1801_86	Lost communication with TCM	Not present
U1A10_86	Lost communication with left radar sensor	Not present
U1A11_86	Lost communication with right radar sensor	Not present

HVAC(Heating Ventilation and Air Conditioning) (1 DTC)

DTC	Description	Status
U0100_00	Lost communication with ECM	Not present

HLAL(Head Lamp Auto Leveling) (1 DTC)

DTC	Description	Status
U0100_00	Lost communication with ECM for brake signal	Not present

Technician Notes
2017315998

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.