Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Fortuner/--
VIN: AHTCB3GS002015735

Odometer Reading: 156660
License Plate: FPW825L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (15)

System		Status/DTC
Engine and transmission		0
Brake		0
SRS airbag		1
Combination meter		1
Air conditioner		0
Headlamp auto leveling	ADAS	1
Entry&Start		0
Power source control		0
Starting control		0
Navigation system		2
Clearance sonar	ADAS	1
Central gateway		0
PPS		1
4WD		0
Radar cruise 1	ADAS	0

DTC (7)

SRS airbag (1 DTC)

DTC	Description	Status
B1826	Side squib (left) circuit open	History

Combination meter (1 DTC)

DTC	Description	Status

B150A	Lost communication with HMI-LAN	History

Headlamp auto leveling (1 DTC)

DTC	Description	Status
B2416	Height control sensor	History

Navigation system (2 DTCs)

DTC	Description	Status
C1622	Rear camera disconnected	History
B157D	Digital audio broadcasting (DAB) antenna disconnected	History

Clearance sonar (1 DTC)

DTC	Description	Status
C1AED	Rear sensor communication circuit	History

PPS (1 DTC)

DTC	Description	Status
U012987	Lost communication with brake system control module missing message	Confirmed

Technician Notes

2017317486

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.