Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261027102743
Test Time: 2026-10-27 10:27:43
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--
VIN: AHTGA3DC900874013

Odometer Reading: 286077km
License Plate: KD21GHGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System		Status/DTC
Engine and ECT		2
ABS/VSC/TRC		1
SRS airbag		4
Combination meter		1
Navigation system		1
Headlamp auto leveling	ADAS	3
Radar cruise 1	ADAS	0
4WD		0

DTC (12)

Engine and ECT (2 DTCs)

DTC	Description	Status
P1608	Engine lack of power	Current
P1608	Engine lack of power	History

ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	History

SRS airbag (4 DTCs)

DTC	Description	Status
B1821	Side squib (right) circuit open	Current
B1905	Left pretensioner squib circuit short	Current
B1821	Side squib (right) circuit open	History
B1905	Left pretensioner squib circuit short	History

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Navigation system (1 DTC)

DTC	Description	Status
U0100	Engine/EV electronic control unit(ECU) communication	History

Headlamp auto leveling (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
B2430	Left LED headlight abnormal	History
B2431	Right LED headlamp abnormal	History

Technician Notes

2017317655

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.