Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261012143405
Test Time: 2026-10-12 14:34:05
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Fortuner/--
VIN: AHTJA3GS600242479
Odometer Reading: 127382km
License Plate: LG85YNGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
Engine and transmission	0
Brake	0
SRS airbag	0
Combination meter	1
Back door	1
Air conditioner	5
Headlamp auto leveling	0
Entry&Start	1
Power source control	0
Starting control	0
Navigation system	0
Clearance sonar	1
Central gateway	0
PPS	0
4WD	0
Radar cruise 1	0

DTC (9)

Combination meter (1 DTC)

DTC	Description	Status
B150A	Lost communication with HMI-LAN	History

Back door (1 DTC)

DTC	Description	Status
B2250	Power back door(PBD)/PTL closer operation	History

Air conditioner (5 DTCs)

DTC	Description	Status
B1441	Air mix damper control servomotor circuit (passenger)	History
B1442	Air inlet damper control servomotor	History
B1443	Air outlet damper control servomotor circuit	History
B1446	Air mix damper control servomotor circuit (driver)	History
B1497	Communication fault (bus IC)	History

Entry&Start (1 DTC)

DTC	Description	Status
U0155	Lost communication with instrument panel cluster (IPC) control module	History

Clearance sonar (1 DTC)

DTC	Description	Status
C1AE1	Left front sensor	History

Technician Notes

2017310759

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.