Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261028135250
Test Time: 2026-10-28 13:52:50
Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Starlet/--
VIN: JTDGWC52S00826960
Odometer Reading: 133450
License Plate: KXC834MP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	2
EPS(Power steering)	0
BCM(Body Control Module)	2
SMK(Immobilizer and/or keyless system)	2

DTC (6)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1057	Power supply voltage	History
C1023	Yaw Rate Sensor (YRS) circuit performance	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
B1157	Airbag impact signal input	History
U0151	Lost communication with restraints control module	History

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
B1157	Airbag impact signal input	History
U0151	Lost communication with restraints control module	History

Technician Notes

2017318690

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.