Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Urban Cruiser/--
VIN: JTDPYGJ1S00979739

Odometer Reading: 95755
License Plate: LX50DRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
ECM/PCM(Engine/powertrain)	1
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	1
SRS(Airbag)	1
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	5
CGW(Central gateway control module)	0
EPS(Power steering)	0
A/C(Air-Conditioning)	3
BCM(Body Control Module)	0
IMMO(Immobilizer and/or keyless system)	9

DTC (20)

ECM/PCM(Engine/powertrain) (1 DTC)

DTC	Description	Status
P1642	Immobilizer communication line error	History

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1057	Power supply voltage	History

SRS(Airbag) (1 DTC)

DTC	Description	Status
B1004-18	Power source voltage too low	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (5 DTCs)

DTC	Description	Status
B1801	Power source voltage too high	History

B1864	Left rear parking sensor	History
B1865	Rear/center/left parking sensor	History
B1866	Rear/center/right parking sensor	History
B1867	Right rear parking sensor	History

A/C(Air-Conditioning) (3 DTCs)

DTC	Description	Status
B1513	Temperature control actuator (motor) and/or its circuit fault	History
B1514	Air flow control actuator (motor) fault	History
B1531	Air intake control actuator error	History

IMMO(Immobilizer and/or keyless system) (9 DTCs)

DTC	Description	Status
B1134	Remote controller battery low	History
B115B	Steering lock unit circuit	History
B1189	Immobilizer antenna communication fault	History
B1192	Ignition 1 relay fault	History
B1461	Vehicle speed signal inconsistent	History
U0100	Lost communication with ECM	History
U0121	Lost communication with ABS or electronic stability program control module	History
U0140	Lost communication with BCM	History
U0155	Lost communication with Instrument Panel Cluster (IPC) control module	History

Technician Notes

2017315194

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.