HAVAL VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HAVAL/Haval H2/2019 (China 6)/--
VIN: LGWEE4A46KH901241

Odometer Reading: 135508
License Plate: HT40VVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ECM (Engine Control Module)	0
A/T (Automatic Transmission)-Transmission control system (6AT)	0
ESP (Electronic Stability Program)	1
SRS (Supplemental Restraint System)	5
BCM (Body Control Module)	6
ICM/IP (Instrument Cluster Module/Instrument Pannel)	0
A/C (Air Conditioning) -A/C (Air Conditioning) - Red Logo	0
PEPS (Passive Start System)	7
GW (Gateway)-Gateway - Continental	2
ESCL (Electronic Steering Column Lock)	3
EPS (Electric Power Steering)-EPS (Electric Power Steering)	4
SAS (Steering Angle Sensor)	1
CMS (CAN Signal Conversion System)	0

DTC (29)

ESP (Electronic Stability Program) (1 DTC)

DTC	Description	Status
C190104	Processor voltage too low	History DTC

SRS (Supplemental Restraint System) (5 DTCs)

DTC	Description	Status
B10161B	Passenger curtain airbag too high	Current DTC
B10151B	Passenger side airbag too high	History DTC
B103414	Crash Output of Controller Short to GND or Open	History DTC
U110116	Power supply voltage too low	History DTC
U014687	GW communication lost	History DTC

BCM (Body Control Module) (6 DTCs)

DTC	Description	Status
B14CD02	Rear right tire pressure low	Current DTC
U110116	Voltage too low	History DTC
B148A04	RLS error	History DTC
B148B01	RLS hardware error	History DTC
B148C01	RLS light sensor error	History DTC
B149404	Rear PAS response error	History DTC

PEPS (Passive Start System) (7 DTCs)

DTC	Description	Status
B140715	Keyless entry antenna 2 short to power or open circuit	Current DTC
B140D13	Front passenger door handle sensor open circuit	Current DTC
B140004	Internal Fault	History DTC
B142111	IGN1 relay short to ground	History DTC
B141549	Immobilizer coil fault	History DTC
U110116	Under-voltage fault diagnosis	History DTC
U300416	Power supply 1 lost	History DTC

GW (Gateway)-Gateway - Continental (2 DTCs)

DTC	Description	Status
U100287	PEPS lost	History DTC
U110187	Communication voltage too low	History DTC

ESCL (Electronic Steering Column Lock) (3 DTCs)

DTC	Description	Status
U110016	Voltage too low	History DTC
U100587	NMLimphome	History DTC
U014087	Communication with BCM lost	History DTC

EPS (Electric Power Steering)-EPS (Electric Power Steering) (4 DTCs)

DTC	Description	Status
C100400	Supply voltage below hazard value	History DTC

C100B00	ECU abnormal shutdown	History DTC
U010087	ECM lost	History DTC
U110116	Undervoltage	History DTC

SAS (Steering Angle Sensor) (1 DTC)

DTC	Description	Status
C160811	Steering angle sensor input power undervoltage	History DTC

Technician Notes

2017315737

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.