Chery VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chery/Tiggo series/Tiggo 5x/Tiggo 4/Tiggo 4 Pro/Tiggo Cross/Tiggo 5x/DR 4.0/DR 5.0/Sportequipe 5/MVM X55/MVM X55 Pro/--

Odometer Reading: 59655

VIN: LVVDB21B3PD975723

License Plate: HFL044L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V14.60

Repair Order Number: --

System Scanned (15)

System	Status/DTC
ECM (Engine system)	0
AT (Automatic Transmission System)-Continuously Variable Transmission (CVT25)	2
SRS (Supplementary Restraint System)-SRS-AIR BAG	2
IC (Instrument Cluster)-Combination instrument system	0
Tire Pressure Monitoring System (TPMS)-TPMS (Tire Pressure Monitoring System)	1
BCM (Body control system)-BDM (Body Domain Module)	4
AC (Automatic air conditioning system)	0
PEPS (Keyless start system)-PEPS	4
ABS (Anti-lock Brake System)/ESP (Electronic Stability Program)	0
EPS (Electronic Power Steering System)	0
IMMO (Immobilizer)-IMMO (engine immobilizer)	4
PAC (Parking Assist Control) ADAS	0
DVD (Audio Entertainment System)	0
SAS (Steering Angle System)	0
CGW (Central Gateway)	0

DTC (17)

AT (Automatic Transmission System)-Continuously Variable Transmission (CVT25) (2 DTCs)

DTC	Description	Status
P176100	Calibration Data Does Not Match Main Software	History
P088200	TCU(Transmission Control Unit) System Under Voltage	History

SRS (Supplementary Restraint System)-SRS-AIR BAG (2 DTCs)

DTC	Description	Status
B125016	Supply voltage	Circuit voltage below lower limit/History
B124000	Instrument panel airbag light fault	No sub-type fault information/History

Tire Pressure Monitoring System (TPMS)-TPMS (Tire Pressure Monitoring System) (1 DTC)

DTC	Description	Status
B103813	Please refer to vehicle service manual.	Current

BCM (Body control system)-BDM (Body Domain Module) (4 DTCs)

DTC	Description	Status
B152F16	Battery Voltage Low Detection	Historic Fault Code
B150700	IGN-ON input exception (no subtype information)	Historic Fault Code
B150800	ACC input exception (no subtype information)	Historic Fault Code
B152E1D	Boot detection failed	Historic Fault Code

PEPS (Keyless start system)-PEPS (4 DTCs)

DTC	Description	Status
B152F16	Battery voltage low	History
B150700	IGN relay drive circuit abnormal	No sub-type/History
B150800	ACC relay drive circuit abnormal	No sub-type/History
B152E1D	Starting failed	History

IMMO (Immobilizer)-IMMO (engine immobilizer) (4 DTCs)

DTC	Description	Status
B152F	Battery voltage too low	Historic Fault Code
B1507	Ignition switch internal fault	Historic Fault Code
B1508	Ignition switch ACC drive fault	Historic Fault Code
B152E	Ignition switch start fault	Historic Fault Code

Technician Notes

2017316055

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.