Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261009144829
Test Time: 2026-10-09 14:48:29
Technician: Werner

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Ciaz/--
VIN: MA3AVC71S00509636

Odometer Reading: 57170
License Plate: MY69JRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	1
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	0
EPS(Power steering)	0
BCM(Body Control Module)	2
SMK(Immobilizer and/or keyless system)	2

DTC (5)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1057	Power supply voltage	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
B1188	Transponder communication fault	History
B1189	Immobilizer antenna communication fault	History

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
B1188	Transponder communication fault	History
B1189	Immobilizer antenna communication fault	History

Technician Notes

2017309718

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.