Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/EcoSport/--
VIN: MAJAXXMRKAEA53612

Odometer Reading: 110736km
License Plate: KPY852MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
PCM(Powertrain control module)	1
TCM(Transmission control module)	0
ABS(Anti-lock brake system)	0
RCM(Restraint control module)	1
IPC(Instrument panel control module)	1
ACM(Audio control module)	0
APIM(Accessory protocol interface module)	0
BdyCM(Body control module) ADAS	4
FCDIM(Front control/display interface module)	0
HVAC(Heating ventilation air conditioning)	1
PSCM(Power steering control module)	0

DTC (8)

PCM(Powertrain control module) (1 DTC)

DTC	Description	Status
P0340:95-AF	Camshaft Position Sensor A Circuit (Bank 1 or single sensor)	CMDTCs

RCM(Restraint control module) (1 DTC)

DTC	Description	Status
B1413:93-08	Driver Frontal Restraints Sensor	CMDTCs

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status

U0257:00-08	Lost Communication With Front Controls / Display Interface Module	CMDTCs

BdyCM(Body control module) (4 DTCs)

DTC	Description	Status
P062F:46-48	Internal Control Module EEPROM Error	CMDTCs
B123A:15-08	Left Front Turn Indicator	CMDTCs
B1D00:15-48	Left Low Beam	CMDTCs
B1D21:62-48	Remote Control Switch	CMDTCs

HVAC(Heating ventilation air conditioning) (1 DTC)

DTC	Description	Status
U3006:16-08	Control Module Input Power A Circuit / Open	CMDTCs

Technician Notes

2017309138

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.