Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261012160219
Test Time: 2026-10-12 16:02:19
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851ALJM869327

Odometer Reading: 103768
License Plate: HR41NVGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	2
AB (Airbag)	3
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
EPS (Motor Driven Power Steering)	0

DTC (6)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0704	Clutch switch input circuit fault	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102	Battery voltage low	History
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History
B2505:00	Passenger airbag (PAB) On/Off warning lamp failure	History

Technician Notes

2017310690

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.