Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250512151657
Test Time: 2025-05-12 15:16:57
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51BLLM731056
Odometer Reading: 141167km
License Plate: JK88SMGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.86
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	0
ABS (Anti Lock Brake)	0
AB (Airbag)	10
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	0
BCM (Body Control)	0

DTC (10)

AB (Airbag) (10 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1329:00	Driver front impact sensor (FIS) communication error	History
B1334:00	Passenger front impact sensor (FIS) communication error	History
B1346:00	Driver airbag (DAB) resistance too high (1st Stage)	History
B1352:00	Passenger airbag (PAB) resistance too high (1st Stage)	History
B1361:00	Front driver pretensioner resistance too high	History
B1367:00	Front passenger pretensioner resistance too high	History
B1527:00	Passenger airbag (PAB) On/Off switch circuit open or short to battery	History
B2500:00	Warning lamp failure	History

B2505:00 Passenger airbag (PAB) On/Off warning lamp failure History

Technician Notes

2016874733

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.