Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026154521
Test Time: 2026-10-26 15:45:21
Technician: Barney

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00391462

Odometer Reading: 83696
License Plate: JB62NGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
TCM(Transmission Control Module)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	1
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	3
EPS(Power steering)	0
BCM(Body Control Module)	0
SMK(Immobilizer and/or keyless system)	0

DTC (4)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1057	Power supply voltage	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM	History
U0101	Lost communication with Transmission Control Module (TCM)	History
U0121	Lost communication with ABS or electronic stability program control module	History

Technician Notes

2017317349

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.