Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00A21310

Odometer Reading: 79413
License Plate: KT75YPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	3
SRS(Airbag)	1
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	3
CGW(Central gateway control module)	0
EPS(Power steering)	0
BCM(Body Control Module)	0
SMK(Immobilizer and/or keyless system)	0

DTC (7)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1057	Power supply voltage	History
C1037	Steering angle sensor power supply voltage	History
C1091	CAN invalid data from ECM	History

SRS(Airbag) (1 DTC)

DTC	Description	Status
B1004-18	Power source voltage too low	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (3 DTCs)

DTC	Description	Status
B1840	Vehicle speed data invalid	History
U0100	Lost communication with ECM	History

U0121	Lost communication with ABS or electronic stability program control module	History

Technician Notes

2017316614

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.