# Suzuki VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00C14115

Odometer Reading: 58405
License Plate: LF73VGGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 8 )

| System | Status/DTC |
|---|---|
| ECM/PCM(Engine/powertrain) | 0 |
| ABS/ESP(Anti-lock Braking System / Electronic Stability Program) | 6 |
| SRS(Airbag) | 1 |
| IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) | 3 |
| CGW(Central gateway control module) | 5 |
| EPS(Power steering) | 2 |
| BCM(Body Control Module) | 2 |
| SMK(Immobilizer and/or keyless system) | 2 |

## DTC ( 21 )

### ABS/ESP(Anti-lock Braking System / Electronic Stability Program) ( 6 DTCs )

| DTC | Description | Status |
|---|---|---|
| C1057 | Power supply voltage | History |
| C1037 | Steering angle sensor power supply voltage | History |
| U0126 | Lost communication with steering angle sensor module | History |
| U0100 | Lost communication with ECM | History |
| C1091 | CAN invalid data from ECM | History |
| C1024 | Steering angle sensor circuit performance | History |

### SRS(Airbag) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| B1004-18 | Power source voltage too low | History |

### IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|

| | | |
|---|---|---|
| B1840 | Vehicle speed data invalid | History |
| U0131 | Lost communication with Power Steering Control Module (PSCM) | History |
| U0151 | Lost communication with restraints control module | History |

## CGW(Central gateway control module) ( 5 DTCs )

| DTC | Description | Status |
|---|---|---|
| U0100-87 | Lost communication with ECM | History |
| U0151-87 | Lost communication with restraints control module | History |
| U0121-87 | Lost communication with ABS or electronic stability program control module | History |
| U0155-87 | Lost communication with Instrument Panel Cluster (IPC) control module | History |
| U0126-87 | Lost communication with steering angle sensor module | History |

## EPS(Power steering) ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| C1161 | CAN invalid data from vehicle speed | History |
| C1166 | Reliability defect of vehicle speed data | History |

## BCM(Body Control Module) ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| U0100 | Lost communication with ECM | History |
| U0151 | Lost communication with restraints control module | History |

## SMK(Immobilizer and/or keyless system) ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| U0100 | Lost communication with ECM | History |
| U0151 | Lost communication with restraints control module | History |

## Technician Notes

2017316381

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*