Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261007124628
Test Time: 2026-10-07 12:46:28
Technician: Andrick

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00700054801
Odometer Reading: 178937km
License Plate: KR58XZGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
INJ(Injection)	18
ABS(Anti-lock braking system)	6
ABG(Airbag / pretensioners)	3
TDB(Instrument panel)	4
UCH(Central control unit)	2
UCC(Communications unit) ADAS	1
DAV(Variable power assist steering)	5
GW2(Central gateway)	0
HFM(Hands-free module)	4

DTC (43)

INJ(Injection) (18 DTCs)

DTC	Description	Status
DTC001177	Inlet camshaft shifter Command impossible	Memory
DTC001477	Exhaust camshaft shifter circuit Command impossible	Memory
DTC001492	Exhaust camshaft shifter circuit Performance down or incorrect operation	Memory
DTC01061C	Inlet pressure consistency Abnormal voltage.	Memory
DTC011517	Water temperature sensor circuit Voltage too high.	Memory

DTC017009	Fuel circuit functional fault Component failures	Memory
DTC035111	Cylinder 1 ignition coil circuit Short circuit to earth.	Memory
DTC035113	Cylinder 1 ignition coil circuit Open circuit	Memory
DTC036564	Exhaust camshaft position Signal plausibility failure	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTC250421	Battery voltage 12 V Signal amplitude < minimum	Memory
DTC250479	Battery voltage 12 V Mechanical failures	Memory
DTCC12187	Multiplexed traction control connection Missing message	Memory
DTCC31582	Vehicle speed multiplexed information Sequence counter active/incorrect/not updated	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (6 DTCs)

DTC	Description	Status
DTC403097	Front left wheel target Component or system operation blocked or jammed	Memory
DTC40311D	Front left hand wheel speed sensor circuit Short circuit	Memory
DTC403138	Front left wheel speed sensor frequency Fault on wheel speed sensor circuit	Memory
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory

DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D224	Warning light circuit fault Signal high	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory

TDB(Instrument panel) (4 DTCs)

DTC	Description	Status
DTC94037B	Brake fluid level circuit Below the min level	Memory
DTC941112	Oil pressure sensor circuit Short-circuit to +12V	Memory
DTC941113	Oil pressure sensor circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC920F16	Voltage control Circuit voltage below threshold	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Memory

UCC(Communications unit) (1 DTC)

DTC	Description	Status
DTCC07588	CAN-ext communication Bus off	Memory

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560117	Computer power supply Battery voltage too high	Memory
DTC560849	Computer Internal electronic failure	Memory

DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory

HFM(Hands-free module) (4 DTCs)

DTC	Description	Status
DTCA05111	VER(Steering lock) Short circuit to earth.	Memory
DTCA05267	Steering column lock protection	Memory
DTCA0571C	Steering column lock protection Circuit voltage outside limits	Memory
DTCA05985	Steering column lock protection Signal above the authorised threshold	Memory

Technician Notes

2017308422

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.