BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/2'/220i_B48/--
VIN: WBA2H52020VD46209

Odometer Reading: 171144km
License Plate: HH04BWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V26.01

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (18)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	1
EGS (Electronic Transmission Management)	0
DSC (Dynamic Stability Control)	0
ACSM (Airbag-Advanced Crash Safety Module)	0
KOMBI (Instrument Cluster)	0
FEM (Front Electronic Module)	3
ZGM (Central Gateway Module)	2
ICM (Integrated Chassis Management)	1
EPS (Electric Power Steering)	0
FLEL (Frontal Light Electronics Left) ADAS	0
FLER (Frontal Light Electronics Right) ADAS	0
FZD (Roof Function Center)	1
GWS (Gear Selector Switch)	0
TCB (Combox Emergency Call)	2
HUB (Headunit Basis)	2
CON (Controller)	0
REM (Rear Electronic Module)	1
IHKA (Integrated Automatic Heating And A/C System)	0

DTC (13)

DME (Engine-Digital Motor Electronics) (1 DTC)

DTC	Description	Status
1F0549	Check Control message (ID 2064): Service requires engine oil!	Permanent

FEM (Front Electronic Module) (3 DTCs)

DTC	Description	Status
80416D	Engine compartment lid contact switch: Open during driving	Intermittent
8041B2	Startability limit reached with lights active during stationary operation	Intermittent
804415	Radio remote control: Battery undervoltage	Permanent

ZGM (Central Gateway Module) (2 DTCs)

DTC	Description	Status
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent
801C20	ZGM: central fault memory full - no control-unit fault	Permanent

ICM (Integrated Chassis Management) (1 DTC)

DTC	Description	Status
D02D58	Signal (wheel torque powertrain 1, 41.3.4) invalid, transmitter DME / DDE	Intermittent

FZD (Roof Function Center) (1 DTC)

DTC	Description	Status
801A55	DWA: The alarm has been activated	Permanent

TCB (Combox Emergency Call) (2 DTCs)

DTC	Description	Status
031786	TCB: Functional limitation of Last State Call	Intermittent
B7F341	Emergency battery: Hardware faulty	Intermittent

HUB (Headunit Basis) (2 DTCs)

DTC	Description	Status
B7F8C6	CID: Reduction in brightness due to excess temperature	Intermittent
E1C600	HU-B: Ethernet: Unexpected communication termination	Intermittent

REM (Rear Electronic Module) (1 DTC)

DTC	Description	Status
804890	Turn signal plausibility check failed: Function deactivated	Intermittent

Technician Notes

2017323566

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.