Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261118105453
Test Time: 2026-11-18 10:54:53
Technician: Andrick

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mercedes-Benz/C (205)/--
VIN: WDD2050042R038726

Odometer Reading: 285954km
License Plate: FK43BCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V19.33

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (41)

System	Status/DTC
ECM(Engine Control Unit)	1
TCM(Transmission Control Unit)	0
ESP(Electronically controlled vehicle stability braking system control unit)	3
SRS(Supplemental Restraint System Control Unit)	0
KI(Instrument Cluster)	0
TPM(Tire Pressure Monitor Control Unit)	1
SAMF(Front SAM signal acquisition control unit)	1
LIN:BSN(Battery Sensor)	0
LIN:DBE-1(Sunroof Control Unit)	1
LIN:FSW(Wiper Motor)	0
LIN:VCS(Rain/sunlight sensor)	0
SAMR(Rear SAM signal acquisition control unit)	0
EZS(Electronic Ignition Lock Control Unit)	0
ES(Electric Power Steering)	2
KLA(Air Conditioner Control Unit)	2
PTCU(Drivetrain Control Unit)	0
HU(Head Unit Control Unit)	0
ISM(Shift Lever Control Unit)	1
KG(Keyless Go Control Unit)	0
ABA(Collision Prevention Assist) ADAS	2

DMFL(Left Front Door Control Unit)	0
DMFR(Right Front Door Control Unit)	0
DMRR(Right Rear Door Control Unit)	0
DMRL(Left Rear Door Control Unit)	0
ZBE(Head Unit Display)	0
LIN:OBF(Upper Control Panel)	0
LIN:UBF-S(Head Unit Audio Operation Switch)	0
LIN:UBFL(Head Unit Controller Left Button)	0
LIN:UBFR(Head Unit Controller Right Button)	0
TPAD(TPAD)	1
LIN:UBFL_2(Head Unit Controller Left Button)	0
LIN:UBFR_2(Head Unit Controller Right Button)	0
ZAN(Center Display Control Unit)	0
RBTMFR(Right Front Seat Belt Tensioner Control Unit)	0
RBTMFL(Left Front Seat Belt Tensioner Control Unit)	0
PSD(Sunroof Control Unit)	2
MRM(Steering Column Control Unit)	0
HKS(Trunk Lid Control Unit)	0
FSCU(Fuel Pump Control Unit)	0
EDW(Interior Protection System Control Unit)	0
LIN:AS(Alarm Siren)	0

DTC (17)

ECM(Engine Control Unit) (1 DTC)

DTC	Description	Status
U041208	Implausible data were received from 'Battery'. There is a signal fault or the message is faulty.	Stored

ESP(Electronically controlled vehicle stability braking system control unit) (3 DTCs)

DTC	Description	Status
C053BFE	The power supply of the valves in the ESP/regenerative braking system has an electrical fault or an open circuit.	Stored(Event codes)

U11A5E8	Communication with sensor 'Yaw rate, lateral and longitudinal acceleration' has a malfunction.	Stored(Event codes)
U0101FA	Communication with 'Transmission' has a malfunction.	Stored(Event codes)

TPM(Tire Pressure Monitor Control Unit) (1 DTC)

DTC	Description	Status
C159916	The battery of the tire pressure sensor has a fault.	Active and stored

SAMF(Front SAM signal acquisition control unit) (1 DTC)

DTC	Description	Status
B1F4500	The starter battery has excessive resistance.	Active and stored

LIN:DBE-1(Sunroof Control Unit) (1 DTC)

DTC	Description	Status
B22A31C	'Overhead control panel' has a malfunction. The voltage value is outside the permissible range.	Stored(Event codes)

ES(Electric Power Steering) (2 DTCs)

DTC	Description	Status
B210F00	Input 'Circuit 30' has a malfunction.	Stored(Event codes)
U041600	Implausible data were received from 'Traction system'.	Stored(Event codes)

KLA(Air Conditioner Control Unit) (2 DTCs)

DTC	Description	Status
B10A207	Left blend air flap servomotor fault - mechanical fault	Active and stored
B10A907	Right blend air flap servomotor fault - mechanical fault	Active and stored

ISM(Shift Lever Control Unit) (1 DTC)

DTC	Description	Status
P179D00	The redundancy system for DIRECT SELECT was activated.	Stored(Event codes)

ABA(Collision Prevention Assist) (2 DTCs)

DTC	Description	Status
C10C755	'Collision prevention assist' control unit fault - component not configured	Stored
U0416FD	Implausible data were received from 'Traction system'.	Stored(Event codes)

TPAD(TPAD) (1 DTC)

DTC	Description	Status
B1F6647	'Touchpad' has a malfunction. There is a runtime error.	Stored(Event codes)

PSD(Sunroof Control Unit) (2 DTCs)

DTC	Description	Status

U014187	Communication with the front signal acquisition and actuation module has a malfunction. The message is missing.	Stored(Event codes)
U016887	Communication with the electronic ignition lock has a malfunction. The message is missing.	Stored(Event codes)

Technician Notes

2017327009

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.