Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023155623
Test Time: 2026-10-23 15:56:23
Technician: Werner

Volkswagen CV VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen CV/SG/SF - Transporter/Multivan 2016>/--
VIN: WV2ZZZ7HZHH098875

Odometer Reading: 384440km
License Plate: HM99RPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (12)

System	Status/DTC
01 - Engine Control Module 1	8
03 - Brakes 1	1
04 - Steering Angle Sender	1
08 - Air conditioning	4
09 - Electronic central electric	12
15 - Airbag	2
17 - Instrument cluster	1
19 - Gateway	1
25 - Immobilizer	0
56 - Radio	2
61 - Battery Regulation	0
69 - Trailer Function	1

DTC (33)

01 - Engine Control Module 1 (8 DTCs)

DTC	Description	Status
P023600	Turbocharger boost sensor (A) circuit ,Range/performance	Passive/Sporadic
P261A00	Coolant pump 2 ,Open circuit	Active/static
P010400	Mass or Volume Air Flow Sensor 'A' Circuit Intermittent	Passive/Sporadic
P010100	Mass or Volume Air Flow Sensor 'A' Circuit Range/Performance	Passive/Sporadic
P011300	Intake air temperature sensor 1 (bank 1) ,Circuit high	Passive/Sporadic
P067100	Cylinder 1 Glow Plug Circuit	Active/static

P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic
U140A00	Terminal 30 ,Open circuit	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

08 - Air conditioning (4 DTCs)

DTC	Description	Status
B108F71	Temperature flap motor ,Actuator stuck	Passive/Sporadic
U111300	Function limitation due to received malfunction value	Passive/Sporadic
B10A915	Activation A/C compressor ,Open circuit/short circuit to B+	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

09 - Electronic central electric (12 DTCs)

DTC	Description	Status
01365:008	Lock/unlock switch/interior locking switch - Implausible signal	Passive/Sporadic
03224:000	Play protection active	Passive/Sporadic
00975:011	Rear window defogger - Open circuit	Active/static
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00538:011	Reference voltage - Open circuit	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic
03589:014	Driver side window regulator switch - Faulty	Passive/Sporadic
00936:014	Window lift switch, frt. pass. side - Faulty	Passive/Sporadic
02746:010	Right daytime running lamp bulb - Open circuit/short circuit to B+	Active/static
03184:007	Terminal 58st - Short circuit to ground	Passive/Sporadic
02195:008	Instrument panel lighting dimmer switch - Implausible signal	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

B13BCF2	Multiple collision brake ,No function	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01044:000	Control module incorrectly coded	Passive/Sporadic

69 - Trailer Function (1 DTC)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

Technician Notes

2017316738

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.