



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	28/09/2026		M57 Pretoria Road - 1619
Inspection Date	28/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KJY392MP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2019-2021]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6RZLU006847	Last COR	
Engine Number		License Expiry Date	31/07/2026
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	TWO COAT UNI
Year Model	2020	Fuel	PETROL
Km Reading	260,870 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Damage	Repair Way
Engine Wiring Defective	Repair
Hoses Water Leak	Replace
Radiator Damaged	Replace
Bonnet cable Defective	Repair
Radio/CD/USB Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Replace
Switch Electrical Window Winder front left Damaged	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Parcel Tray Missing	Replace
Gear Lever Dust Boot Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
B • Pillar Right Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Roof Paintwork • Scratched	Repair
Steering Rack Boot Left Damaged	Replace
Steering Rack Boot Right Damaged	Replace
Rear Axle Welded	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Spare Tyre Damaged	Replace
Rim Front Right Dented	Repair
Rim Spare Wheel Dented	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Replace
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Repair
Fuel Tank Damaged	Repair
Fuel Lines Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Steering Loose / Excessive Play	Repair
Brakes Insufficient	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026

Damage	Repair Way
Engine Performance Idling / Hunting	Repair
Wheel Spanner Missing	Replace
Warning light illuminated on dashboard	Repair
Driver's electrical window switch unit loose	Repair
Antenna housing damaged	Replace
Deceleration service brake defective	Repair
Engine oil sump damaged	Repair
Center exhaust cross member bracket damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.11	2.27	-	
Rear	1.62	1.54	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/70 R14	84H	Durun	Radial	V	0224	0 mm
Front Right	175/70 R14	84H	Dunlop	Sp-Touring	V	2224	0 mm
Rear Left	175/70 R14	84T	Westlake	Radial	V	0424	3 mm
Rear Right	175/70 R14	84T	Annaite	Anchee	V	0424	2 mm
Spare	175/70 R14	85H	Durun	Radial	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P0130:00/0304:000	O2 SENSOR CIRC.,BANK1-SENSOR1 MALFUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR,

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026

ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Radiator and Aircon condenser loose.
Interior: Vehicle interior dirty and panels scratched.Bonnet release handle and plastic cover missing.
Body • Exterior: Dents and scratches on body panelsBody panels misaligned.Signs of impact damage to front of vehicle.
Axle and Suspension: Front and rear suspension faulty.Signs of vehicle grabbing.
Road Test: Vehicle unsafe to drive

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026

Vehicle Information			
Name/Car:	Car	Make/Model:	2017 VW Polo
Registration:	2017/2021	Engine:	1.4 TSI
Year:	2017	Transmission:	5-Speed Manual
Inspection Results			
Brake System	Pass	Shock Absorbers	Pass
Steering	Pass	Wheels/Tyres	Pass
Lighting	Pass	Bodywork	Pass
Engine/Exhaust	Pass	Interior	Pass
Overall Condition	Pass	Final Remarks	Vehicle in good condition.

Brake and shock absorber report

AUTEL	
Volkswagen VEHICLE DIAGNOSTIC REPORT	
Vehicle Info:	2017 Volkswagen Polo 1.4 TSI
Engine:	1.4 TSI
Transmission:	5-Speed Manual
Brake System:	Pass
Shock Absorbers:	Pass
Wheels/Tyres:	Pass
Lighting:	Pass
Bodywork:	Pass
Engine/Exhaust:	Pass
Interior:	Pass
Overall Condition:	Pass

Diagnostic report page 1

AUTEL	
Volkswagen VEHICLE DIAGNOSTIC REPORT	
Vehicle Info:	2017 Volkswagen Polo 1.4 TSI
Engine:	1.4 TSI
Transmission:	5-Speed Manual
Brake System:	Pass
Shock Absorbers:	Pass
Wheels/Tyres:	Pass
Lighting:	Pass
Bodywork:	Pass
Engine/Exhaust:	Pass
Interior:	Pass
Overall Condition:	Pass

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026




90 DEGREE LEFT



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026



LICENSE DISC




VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Engine oil sump

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Center exhaust cross member br



Oil cap and dipstick



Driver electrical window switc



Antenna housing



Front Fender Left



Switch Electrical Window Winder front left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026



Seat Front Left



Rear Fender Left



Door Sealing Rubber Rear Left



Seat Rear



Seat Rear



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch door



Rear Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Door Sealing Rubber Rear Right



Seat Rear



Seat Front Right



B • Pillar Right



Center Console / Cubbyhole + Lid



Gear Lever Dust Boot

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026



Hood Lining



Steering Wheel Trim



Radio/CD/USB



Parcel Tray



Spare Tyre



Rim Spare Wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Boot Lid / Hatch Door Rubbers



Tail Light Left



Tail Light Right



Door Front Right



Door Rear Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Front Fender Right



Bonnet



Door Front Left



Door Rear Left



Door Rear Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Bonnet cable



Roof



Front Fender Right / Inner Tray



Rim Front Right



Control Arm Bush(es) Front Axle Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026



Front Bumper



Front Bumper



Sill Panel Left



Control Arm Bush(es) Front Axle Left



Front Fender Left / Inner Tray



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Sub Frame



Engine to silencer pipe



CV Joint(s) Boot(s) Front Left (inner/outer)



Belly plates



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Chassis



Chassis



Fuel Lines



Fuel Tank



Rear Axle



Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:

2017304195

DATE

28/09/2026



Tyre Front Right



Tyre Front Left



Radiator Cradle



Radiator Cradle



Engine Wiring



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZ6RZLU006847



CONDITION REPORT



Report No:
2017304195
DATE
28/09/2026



Steering Rack Boot Left



Steering Rack Boot Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZLU006847