DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	KHZ221MP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6RZMU008980	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT UNI
Year Model	2021	Fuel	PETROL
Km Reading	122,519 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026





Damage	Repair Way
Windscreen Wiper Missing	Replace
Seat Front Left Dirty	Repair
Seat Rear Dirty	Repair
Sun Visor Right Damaged	Repair
Hood Lining Dirty	Repair
Parcel Tray Damaged	Repair
Boot Carpet Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Left Residual Traces of Repair	Repair
B • Pillar Right Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Residual Traces of Repair	Replace
Rear bumper Residual Traces of Repair	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Fuel Flap Residual Traces of Repair	Repair
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Windscreen Chipped	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Right Scratched	Repair
Main Beam Right Damaged	Repair
Radiator Cradle Damaged	Replace
Vehicle license disk missing	Replace
Warning light illuminated on dashboard	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No: 2017314605
DATE 20/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.17	3.24	-	
Rear	1.76	1.93	-	
Emergency / Parking	1.66	1.79	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R15	84H	Dunlop	Sp-Touring	V	3525	4 mm
Front Right	185/60 R15	84H	Dunlop	Sp-Touring	V	3625	4 mm
Rear Left	185/60 R15	88H	Goodyear	Efficient	V	2022	0 mm
Rear Right	185/60 R15	84H	Continental	Contipremuim	V	2022	3 mm
Spare	185/60 R14	82H	Goodyear	Efficient	V	0621	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	09-ELECTRONIC CENTRAL ELECTRIC	01758:011	LAMPS FOR BRAKE LIGHTS-OPEN CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Signs of impact damage to rear of vehicle.Boot does not close properly.Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Tyres and Rims: Front left center cap missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge,

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026

operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



Oil cap and dipstick



ENGINE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026




Front chassis



Rear chassis



Spare wheel and Accessories



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026




LF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Sun Visor Right



Hood Lining



Steering Wheel Trim



Sill Panel Right



Door Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Door Front Right



Door Front Right




Front Fender Right



Door Front Left



Side Mirror Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Seat Front Left



Sill Panel Left



Seat Rear



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Rear bumper



Rear bumper



Windscreen Wiper



Parcel Tray



C • Pillar Left



C • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Boot Carpet



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Windscreen



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Rim Front Right



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Rim Front Left



Sill Panel Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



Front Bumper



Front Bumper




Rear Fender Right / Inner Tray



Rim Rear Right



Radiator Cradle



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT


Report No:
2017314605
DATE
20/10/2026



Rear Fender Right / Inner Tray



Main Beam Right



Inner Boot Floor Pan and Spare Wheel Well



A • Pillar Right



Water level



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980

DEKRA

CONDITION REPORT

Report No:
2017314605
DATE
20/10/2026



B • Pillar Left



C • Pillar Left



B • Pillar Right



C • Pillar Right



Fuel Flap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZMU008980