DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park -**
Requested Date	**21/07/2026**		
Inspection Date	**21/07/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**VOLKSWAGEN**	Registration Number	**KG78MJGP**
Model	**POLO VIVO 1.4 55KW TRENDLINE 5-DR [2021-2023]**	Register Number	
		Date Of First Licensing	
VIN	**AAVZZZ6RZNU001861**	Last COR	
Engine Number		License Expiry Date	**31/12/2026**
Doors	**5**	Power / Displacement	
Color	**WHITE**	Paint Finish	**C - COMMON**
Year Model	**2021**	Fuel	**PETROL**
Km Reading	**86,115 KM**	Transmission	**MANUAL**
Cab / Body Type	**HATCHBACK**		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No: 2017273322
DATE 21/07/2026



Damage	Repair Way
Tail Light Left Chipped	Repair
Headlight Left Damaged	Repair
Headlight Right Damaged	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Flaking	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Service Brake Performance Front Axle Left / Right Difference out of legal range	Repair
Radiator Cradle Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	1.5	-	
Rear	1.8	2.0	-	
Emergency / Parking	0.6	1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Goodyear	Efficient gr	V	3821	3 mm
Front Right	185/60R15	84H	Continental	Contact	V	3721	2 mm
Rear Left	185/60R15	88H	Goodyear	Efficient gr	V	2619	3 mm
Rear Right	185/60R15	84H	Continental	Contact	V	3721	2 mm
Spare	185/60R15	84H	Continental	Contact	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE/ SPORADIC	U101100	SUPPLY VOLTAGE VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861


DEKRA

CONDITION REPORT


Report No:
2017273322
DATE
21/07/2026



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861


DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Expention bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026



Oil cap and dipstick




Water level



Headlight Left



Headlight Right



Service Brake Performance Front Axle



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026



Side Mirror Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026


Sill Panel Left


Front Bumper


Front Bumper


Bonnet


Front Fender Right


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861

DEKRA

CONDITION REPORT

Report No:
2017273322
DATE
21/07/2026



Door Rear Right



Rear Fender Right



Sill Panel Right



Radiator Cradle



Tail Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU001861