DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	LL83DYGP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2022-2024]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6RZPU002826	Last COR	
Engine Number		License Expiry Date	31/01/2027
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	TWO COAT UNI
Year Model	2022	Fuel	PETROL
Km Reading	87,210 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026





Damage	Repair Way
Engine Wiring Defective	Repair
Tail Light Left Damaged	Replace
Seat Front Left Dirty	Repair
Seat Rear Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Missing	Replace
Carpet Front Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Damaged	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Damaged	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Spare Tyre Damaged	Replace
Rim Front Left Dented	Repair
Rim Spare Wheel Dented	Repair
Gearbox Oil Sweat	Repair
Radiator Cradle Damaged	Replace
Front bumper stiffener dented	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.21	2.6	-	
Rear	1.63	1.85	-	
Emergency / Parking	1.1	1.01	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R14	82H	Goodyear	Efficient	V	3822	1 mm
Front Right	185/60 R14	82H	Goodyear	Efficient	V	3822	1 mm
Rear Left	185/60 R14	82H	Invovic	EL601	V	4825	4 mm
Rear Right	185/60 R14	82H	Invovic	EL601	V	4825	4 mm
Spare	185/65 R15	88T	Goodyear	Duragrip	V	0617	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	03-BRAKES 1	C102D00	TIRE PRESSURE WARNING	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Rear left and right headrests missing.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826


DEKRA

CONDITION REPORT


Report No:
2017316610
DATE
23/10/2026



Brake and shock absorber test



Diagnostic report page 1




Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Front bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Spare Accessories



Oil cap and dipstick



Door Sealing Rubber Front Right



Seat Rear



Seat Rear



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Door Rear Right



Door Front Right



Door Front Right



Front Fender Right



Front Fender Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Rear Fender Left



Door Rear Left



Door Front Left



Seat Front Left



Tail Light Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Rear bumper



Parcel Tray



Spare Tyre



Spare Tyre



Rim Spare Wheel



Carpet Front

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Bonnet



Bonnet



Engine Wiring



Water level



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Rim Front Left



Front Bumper



Front Bumper



Front Bumper



Radiator Cradle



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826

DEKRA

CONDITION REPORT

Report No:
2017316610
DATE
23/10/2026



Rear Fender Right / Inner Tray



Side Mirror Right



Water level



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU002826