DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	CB18FKGP
Model	POLO VIVO 1.6 BASE 5-DR [2010-2015]	Register Number	
VIN	AAVZZZ6SZDU003875	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	28/02/2027
Color	WHITE	Power / Displacement	
Year Model	2012	Paint Finish	C - COMMON
Km Reading	239,503 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Radiator Damaged	Replace
Center Console / Cubbyhole + Lid Defective	Repair
Windscreen Wiper Worn	Replace
Air Conditioner Insufficient	Repair
Headlight Left Damaged	Replace
Seat Front Right Worn	Repair
Seat Rear Worn	Repair
Door Sealing Rubber Front Left Torn / Cut	Replace
Door Sealing Rubber Front Right Torn / Cut	Replace
Window Winder rear right Broken	Replace
Gear Lever Dust Boot Worn	Replace
Clutch Pedal Rubber Worn	Replace
Front Bumper Damaged	Repair
A • Pillar Right Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Damaged	Repair
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Windscreen Cracked	Replace
Service Brake Performance Front Axle Insufficient	Repair
Stabilizer Mounting Front Right Damaged	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Worn	Replace
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Silencer Damaged	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
CV Joint(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Front Right (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Battery Loose and clamps not fastened	Repair
ECU not properly mounted	Repair
ABS AND BRAKE illuminated	Repair
Rear tyres size differs	Replace
Engine Oil Sump Dented	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No: 2017317658
DATE 27/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.8	2.6	-	
Rear	1.7	1.8	-	
Emergency / Parking	0.7	0.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/70R14	84T	HILO	GENESYS Xp	V	1626	4 mm
Front Right	175/70R14	84T	HILO	GENESYS XP	V	1626	4 mm
Rear Left	165/70R14	85T	ROYALBLACK	ROYALMILE	V	0126	2 mm
Rear Right	185/60R14	82H	FALKEN	ZIEXZE914	V	1621	1 mm
Spare	175/65R14	82T	MICHELIN	ENERGY	V	3416	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE 1	16711:000	KNOCK SENSOR 1 CIRC. LOW INPUT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose
Interior: Driver seat adjustment handle missing

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875


DEKRA

CONDITION REPORT


Report No:
2017317658
DATE
27/10/2026



BRAKE REPORT



DIAGNOSTICS



DIAGNOSTICS



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875


DEKRA

CONDITION REPORT


Report No:
2017317658
DATE
27/10/2026




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASIS



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Battery



ECU



ENGINE OIL SUMP



CLUSTER LIGHTS



OIL CAP AND DIPSTICK



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875


DEKRA

CONDITION REPORT


Report No:
2017317658
DATE
27/10/2026



Air Conditioner



Gear Lever Dust Boot



Clutch Pedal Rubber



Seat Front Right



Door Sealing Rubber Front Right



Door Sealing Rubber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026




Window Winder rear right




Seat Rear



Windscreen Wiper



Windscreen Wiper



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Headlight Left



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Tyre Rear Right



Engine




Gearbox



CV Joint(s) Front Right (inner/outer)



CV Joint(s) Front Left (inner/outer)



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Radiator Cradle



Front Fender Right / Inner Tray



Stabilizer Mounting Front Right



Stabilizer Mounting Front Right



Belly plates



Silencer

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Bolt(s) / Nut(s) Front Wheel Left



Sill Panel Left



Sill Panel Left



Sill Panel Right



Sill Panel Right



Radiator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875


DEKRA

CONDITION REPORT


Report No:
2017317658
DATE
27/10/2026



Door Front Right



Door Rear Right



Front Fender Right



Front Fender Left



Door Front Left



Door Sealing Rubber Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT

Report No:
2017317658
DATE
27/10/2026



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Rear Fender Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875

DEKRA

CONDITION REPORT


Report No:
2017317658
DATE
27/10/2026



A • Pillar Right



Center Console / Cubbyhole + Lid



Service Brake Performance Front Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZDU003875