DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	VOLKSWAGEN	Registration Number	JNG860NW
Model	POLO VIVO GP 1.4 CONCEPTLINE 5-DR [2014-2016]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZFU015228	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	GOLDEN	Paint Finish	TWO COAT UNI
Year Model	2015	Fuel	PETROL
Km Reading	218,015 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Repair
Hoses Water Leak	Replace
Fan Belt Torn / Cut	Replace
Water level Insufficient	Replace
Bonnet cable Damaged	Replace
Central Air Vent Damaged	Replace
Radio/CD/USB Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Missing	Replace
Central Locking Malfunction	Replace
Air Conditioner Insufficient	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Number Plate Light Left Missing	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Belt Rear Right Loose / Excessive Play	Repair
Hood Lining Defective	Repair
Door Handle Front Right Damaged	Replace
Door Handle Rear Left Damaged	Repair
Door Lock Front Right Damaged	Replace
Dash Padding Damaged	Repair
Window Winder front left Defective	Repair
Boot Carpet Damaged	Repair
Boot Panel Left Damaged	Repair
Boot Panel Right Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Damaged	Replace
Door Front Right Damaged	Repair
Door Rear Left Damaged	Replace
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle right Excessive Wear & Tear	Replace
Tie Rod End left Cracked	Replace
Tie Rod End right Cracked	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026

Damage	Repair Way
Shock Absorber Front Right Sweat	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Torn / Cut	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Damaged	Replace
Rim Front Left Damaged	Replace
Rim Rear Right Damaged	Repair
Rim Spare Wheel Dented	Repair
Main Beam Right Dented	Repair
Chassis Damaged	Repair
Sub Frame Dented	Repair
Engine to silencer pipe Damaged	Repair
Silencer Damaged	Replace
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Fuel Tank Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Engine Performance Idling / Hunting	Repair
Engine Noise Excessive	Repair
Triangle Missing	Replace
Gear knob damaged	Replace
Warning lights illuminated on dashboard	Repair
Front right shock absorber weak	Replace
Loose wiring on driver's door	Repair
Rear left quarter window damaged	Replace
Bonnet release handle missing	Replace
Signs of vehicle overheating	Repair
Rear seats and headrests missing	Replace
Center exhaust cross member bracket damaged	Replace
Rear left and right tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	**Braking Force [KN]**	**Axle Weight [KG]**	**Deceleration [m/s²]**
Front	2.07	2.41	-	
Rear	1.78	2.1	-	
Emergency / Parking	1.43	1.66	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92T	Barum	Brillantis	V	1423	0 mm
Front Right	185/65R15	92T	Barum	Brillantis	V	1223	0 mm
Rear Left	185/60R15	84H	Goodyear	Duragrip	V	0718	1 mm
Rear Right	185/65R15	92T	Barum	Brillantis	V	3312	1 mm
Spare	175/70R14	84H	Dunlop	Sp-Sport	V		0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P0571	CRUISE/BRAKE SWITCH (A) CIRC. MALFUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Electrical Components and Instruments: Radio volume switch missing.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray marks on body panels. Dents and scratches on body panels.Boot does not open.
Tyres and Rims: Rear right tyre valve fitted incorrectly
Road Test: Vehicle unsafe to drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Brake and shock absorber repor



Front chassis




Rear chassis



Diagnostic report page 1



Diagnostic report page 2



Diagnostic report page 3

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Exhaust cross member bracket



Engine oil sump




Spare wheel and Accessories



Oil cap and dipstick



Manual Transmission



Loose wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Rear left quarter window



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Front Fender Right



Side Mirror Right



Door Handle Front Right



Steering Wheel Trim



Dash Padding



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Boot Panel Left



Boot Panel Right



Radio/CD/USB



Rim Rear Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Door Front Right



Rear bumper



Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Roof



Roof



Tail Light Right



Tail Light Left



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Seat Front Left



Window Winder front left



Door Handle Rear Left



Bonnet cable



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Headlight Left



Headlight Right



Door Front Left



Rim Front Left



Windscreen Wiper



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Seat Rear



Inner Boot Floor Pan and Spare Wheel Well



Rim Spare Wheel



Spare Tyre



Seat Belt Rear Right



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Windscreen



Engine Wiring



Engine Wiring



Engine Wiring



Fan Belt



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Shock Absorber Front Right



Control Arm Bush(es) Front Axle Right




Brake disc 1. Axle right



Sill Panel Right



Sill Panel Right



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Rear Fender Left / Inner Tray



Sill Panel Left



Sill Panel Left



Front Fender Left / Inner Tray



Control Arm Bush(es) Front Axle Left



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT


Report No:
2017317853
DATE
27/10/2026



Front Bumper


Front Bumper


Front Bumper


Engine to silencer pipe


Engine Wiring


Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026


Chassis


Chassis


Belly plates


Belly plates


Belly plates


Fuel Tank

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Tyre Rear Right



Tyre Rear Left



Silencer



Rear Fender Left / Inner Tray



Inner Boot Floor Pan and Spare Wheel Well



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT


Report No:
2017317853
DATE
27/10/2026



Chassis



Tyre Front Right



Tyre Front Left



Tie Rod End left



Tie Rod End right



CV Joint(s) Boot(s) Front Left (inner/outer)


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right



Gearbox



Main Beam Right



Engine



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Water level



Hoses



Seat Front Right



Side Mirror Left



Door Handle Rear Left



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228

DEKRA

CONDITION REPORT

Report No:
2017317853
DATE
27/10/2026



Central Air Vent



Door Lock Front Right



Central Locking



Number Plate Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZFU015228