DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	KX58YBHP
Model	POLO VIVO GP 1.4 63KW TRENDLINE 5-DR [2016-2018]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZ6SZHU010822	Last COR	
Engine Number		License Expiry Date	30/11/2026
Doors	5	Power / Displacement	
Color	SILVER	Paint Finish	TWO COAT UNI
Year Model	2017	Fuel	PETROL
Km Reading	207,264 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026





Damage	Repair Way
Radio/CD/USB Defective	Repair
Door Handle Front Left Damaged	Replace
Dash Padding Damaged	Repair
Boot Carpet Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Right Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Excessive Wear & Tear	Replace
Brake disc 1. Axle right Excessive Wear & Tear	Replace
Tie Rod End left Cracked	Replace
Tie Rod End right Cracked	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Right Damaged	Replace
Chassis Dented	Repair
Engine to silencer pipe Damaged	Repair
Belly plates Damaged	Replace
Fuel Tank Damaged	Repair
Fuel Lines Defective	Replace
Radiator Cradle Damaged	Replace
Rear left and right tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.34	2.7	-	
Rear	1.59	1.85	-	
Emergency / Parking	1.19	1.42	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	82H	Vinimax	Eco Tour	V	1126	3 mm
Front Right	175/65 R14	82H	Vinmax	Eco Tour	V	1126	3 mm
Rear Left	165/65 R14	79T	General	Altimax	V	4621	2 mm
Rear Right	175/65 R14	82H	Roadking	Argos	V	2725	3 mm
Spare	175/65 R14	82H	Goodyear	Efficient	V	4218	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	25-IMMOBILIZER	01176:007	KEY-SIGNAL TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Computer box strapped with cable ties
Electrical Components and Instruments: Radio volume switch malfunction.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT


Report No:
2017317187
DATE
26/10/2026



Front chassis



Rear chassis



Brake and shock absorber repor



Diagnostic report



Spare wheel and Accessories



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



Dash Padding


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Rear Fender Right



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear bumper



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822


DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Door Front Left



Front Fender Left



Front Fender Left



Side Mirror Left



Side Mirror Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Door Front Right



Bonnet



Bonnet



Door Front Left



Inner Boot Floor Pan and Spare Wheel Well



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026




Water level



Control Arm Bush(es) Front Axle Right



Brake disc 1. Axle right



Brake disc 1. Axle left



Control Arm Bush(es) Front Axle Left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Front Bumper



Front Bumper



Sill Panel Right



Engine to silencer pipe



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Fuel Lines



Fuel Tank




Tyre Rear Right



Belly plates



Belly plates



Tie Rod End left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822

DEKRA

CONDITION REPORT

Report No:
2017317187
DATE
26/10/2026



Tie Rod End right



Radiator Cradle



Water level



Door Handle Front Left



Radio/CD/USB

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZHU010822