DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	17/11/2026		
Inspection Date	17/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KTS844NW
Model	POLO 1.0 TSI 70KW TRENDLINE 5-DR [2019-2021]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZLU035456	Last COR	
Engine Number		License Expiry Date	31/01/2027
Doors	5	Power / Displacement	
Color	BROWN	Paint Finish	TWO COAT METALLIC
Year Model	2020	Fuel	PETROL
Km Reading	252,440 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Repair
Hoses Damaged	Replace
Radiator Leak	Replace
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Replace
Seat Front Right Damaged	Repair
Hood Lining Damaged	Repair
Window Winder rear left Damaged	Replace
Window Winder rear right Damaged	Replace
Steering Wheel Trim Damaged	Replace
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Right Damaged	Replace
Roof Damaged	Replace
Windscreen Damaged	Replace
Rear Axle Damaged	Replace
Rim Front Right Damaged	Replace
Rim Rear Left Damaged	Replace
Radiator Cradle Damaged	Repair
Engine Performance Insufficient	Repair
Engine Noise Idling / Hunting	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	**Braking Force [KN]**	**Axle Weight [KG]**	**Deceleration [m/s²]**
Front	2.78	2.8	-	
Rear	2.44	2.51	-	
Emergency / Parking	1.23	1.26	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/70R14	88T	Annaite	Radial	V	3524	2 mm
Front Right	205/45R17	88W	Royal black	Radial	V	4525	1 mm
Rear Left	205/45R17	88W	Royal Black	Radial	V	4525	2 mm
Rear Right	205/45R17	88W	Royal black	Radial	V	4525	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01 -ENGINE CONTROL MODULE 1	P019700	OIL TEMOERATURE SENSOR, SHORT CIRCUIT TO GROUND	ACTIVE/ STATIC

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: electric windows do not work. vehicle electronics malfunctioning.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Repair work done to vehicle below standard. Vehicle body in poor condition. hatch door does not open. signs of impact damage to front of vehicle. signs of impact damage to rear of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456


DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026




Brake test.




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Undercarriage rear.



Oil cap and dipstick.



Water level



Hoses



Hoses



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Radiator




Headlight Right



Front Bumper



Front Bumper



Grill



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Boot Lid / Hatch door



Door Rear Right



Door Front Right



Front Fender Right



Rear Fender Right



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026


Windscreen


Seat Front Right


Seat Front Left


Hood Lining


Steering Wheel Trim


Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Tail Light Left




Sill Panel Right



Window Winder rear right



Window Winder rear left



Rear Axle



Rear Axle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456


DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Rear Axle



Rear Axle



Engine



Radiator Cradle



Rim Rear Left



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456

DEKRA

CONDITION REPORT

Report No:
2017326458
DATE
17/11/2026



Rim Rear Left



Rim Rear Left



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU035456