DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	03/10/2026		
Inspection Date	03/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	KV36ZZGP
Model	POLO 2.0 TSI 147KW GTI 5-DR DSG [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZMU079518	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	RED	Paint Finish	M - METALLIC
Year Model	2021	Fuel	PETROL
Km Reading	187,775 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026





Damage	Repair Way
Switch Electrical Window Winder rear right Defective	Smart Repair
Seat Front Right Torn / Cut	Repair
Front Bumper Residual Traces of Repair	Repair
Bonnet Dented	Repair
A • Pillar Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch Door Shock Right Defective	Replace
Rear bumper Residual Traces of Repair	Repair
Stabilizer Mounting Front Left Damaged	Replace
Control Arm Bush(es) Front Axle Left Loose / Excessive Play	Replace
Tyre Rear Right Smooth	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Body exterior	Signs of spray work done on body panels
Body exterior	Residual traces of repair on body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.6	3.6	-	
Rear	2.2	1.9	-	
Emergency / Parking	1.3	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R18	92W	Hilo	Vantage	V	3825	5 mm
Front Right	225/40R18	88Y	Goodyear	Eagle	V	2422	2 mm
Rear Left	225/40R18	88Y	Bridgestone	Potenza	V	2119	1 mm
Rear Right	225/40R18	92W	Bridgestone	Potenza	V	4321	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE CONTROL MODULE	P310B00	FUEL LOW PRESSURE REGULATION , FUEL PRESSURE OUT O	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: BOTTOM OF ENGINE AND UNDERCARRIAGE IS FULLY COVERED. ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026




ODOMETER


DASHBOARD (W/ ENGINE RUNNING)


INTERIOR (FRONT DRIVER DOOR)


Automatic transmission


LR TYRE TREAD


RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518


DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026



RF TYRE TREAD



LF TYRE TREAD




No sparewheel



Oil cap and dipstick



Expansion bottle



REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026



ENGINE 1



CHASSIS




ENGINE 2



VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT


Report No:
2017307088
DATE
03/10/2026



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



DIAGNOSTIC REPORT PAGE 3



Seat Front Right



Door Rear Right



Switch Electrical Window Winder rear right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT


Report No:
2017307088
DATE
03/10/2026


Boot Lid / Hatch Door Shock Right


Door Rear Left


Door Front Left


A • Pillar Left


A • Pillar Left


Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026



Bonnet



Front Fender Right



Water level



Door Front Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518

DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026



Front Bumper


Front Bumper


Door Front Left


Stabilizer Mounting Front Left


CV Joint(s) Boot(s) Front Left (inner/outer)


Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518


DEKRA

CONDITION REPORT

Report No:
2017307088
DATE
03/10/2026




Bolt(s) / Nut(s) Rear Wheel Left



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZMU079518