DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/10/2026		
Inspection Date	20/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	KH40GRGP
Model	TIIDA 1.6 VISIA+ 5-DR [2006-2014]	Register Number	
VIN	ADNFCAC11Z2030162	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2011	Paint Finish	TWO COAT UNI
Km Reading	133,595 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026





Damage	Repair Way
Battery box Damaged	Replace
Under bonnet insulation cover Damaged	Repair
Hooter Defective	Repair
Heater control Damaged	Replace
Windscreen Wiper Damaged	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Hood Lining Damaged	Repair
Door Panel Front Left Damaged	Repair
Door Panel Front Right Damaged	Repair
Door Panel Rear Left Damaged	Repair
Dash Padding Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Paintwork • Scratched	Repair
Fuel Flap Defective	Repair
Roof Dented	Repair
Control Arm Bush(es) Front Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Chassis Dented	Repair
Belly plates Damaged	Repair
Airbag warning light intermittent	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.87	2.85	-	
Rear	2.29	2.18	-	
Emergency / Parking	1.23	0.94	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	92H	Sumitomo	HTR H5	V	1721	2 mm
Front Right	185/65 R15	92H	Sumitomo	HTR H5	V	1721	2 mm
Rear Left	185/65 R15	88H	Supercat	Radial	V	3517	2 mm
Rear Right	185/65 R15	88H	Supercat	Radial	V	3417	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P1610	LOCK MODE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose.
Electrical Components and Instruments: Hooter not working.
Lights: Front left and right headlight lenses faded.
Interior: Front and rear seats fully covered
Body • Exterior: Dents and scratches on body panelsBoot does not open.Fuel flap does not close.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026




FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026




ODOMETER


DASHBOARD (W/ ENGINE RUNNING)


INTERIOR (FRONT DRIVER DOOR)


Manual Transmission


LF TYRE TREAD


LR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162


DEKRA

CONDITION REPORT


Report No:
2017314581
DATE
20/10/2026



RR TYRE TREAD



RF TYRE TREAD



Front chassis



Rear chassis



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT


Report No:
2017314581
DATE
20/10/2026




VIN PLATE OR STICKER



LICENSE DISC



DIAGNOSTIC REPORT



SHOCK AND BRAKE REPORT



Door Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Side Mirror Right



Bonnet




Headlight Right



Headlight Left



Windscreen Wiper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Front Fender Left



Side Mirror Left



Door Front Left



Door Front Left



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Rear bumper




Rear bumper



Boot Lid / Hatch door



Heater control


Door Panel Front Right


Under bonnet insulation cover

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Hood Lining



Front Fender Right



Front Fender Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Control Arm Bush(es) Front Axle Left



Belly plates



Chassis



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Water level



Battery box



Door Panel Front Left



Door Panel Rear Left



Hooter



Dash Padding

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162

DEKRA

CONDITION REPORT

Report No:
2017314581
DATE
20/10/2026



Roof



Fuel Flap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNFCAC11Z2030162