DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	NISSAN	Registration Number	KT64LTGP
Model	NP200 1.6 8V BASE +AC SAFETY PU [2011-2025]	Register Number	
		Date Of First Licensing	
VIN	ADNUSN1D5U0210214	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	2	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2022	Fuel	PETROL
Km Reading	149,393 KM	Transmission	MANUAL
Cab / Body Type	SINGLE CAB		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Air cleaner Damaged	Replace
Central Air Vent Damaged	Replace
Radio/CD/USB Missing	Replace
Air Conditioner Insufficient	Replace
Tail Light Left Cracked	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Sun Visor Right Damaged	Repair
Hood Lining Dirty	Repair
Door Lock Front Left Damaged	Replace
Carpet Front Damaged	Repair
Mirror Adjusters Damaged	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Grill Paintwork • Scratched	Repair
Bonnet Damaged	Replace
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Tailgate Damaged	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Residual Traces of Repair	Repair
Load Body Damaged	Repair
Windscreen Cracked	Replace
Speed Sensor Damaged	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Steering Rack Boot Left Damaged	Replace
Steering Rack Boot Right Leak	Replace
Shock Absorber Front Right Sweat	Replace
Wheel bearing Front Left Loose / Excessive Play	Replace
Rear Axle Damaged	Repair
Ball Joint(s) Front Axle Right Loose / Excessive Play	Repair
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026

Damage	Repair Way
Rim Rear Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Main Beam Left Dented	Repair
Main Beam Right Damaged	Repair
Chassis Damaged	Repair
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
Fuel Tank Damaged	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Repair
Engine Noise Excessive	Repair
Triangle Missing	Replace
Right quarter window damaged	Replace
Bonnet release handle damaged	Replace
ABS warning light illuminated on dashboard	Repair
Front bumper stiffener damaged	Replace
Aircon condenser dented	Repair
Front left brake caliper dust plate loose	Replace
Spare wheel missing	Replace
Dipstick holder damaged	Replace
Front and rear tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	3.17	2.71	-	
Rear	1.56	2.05	-	
Emergency / Parking	0.6	1.83	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60 R15	88H	Annaite	AN600	V	0524	3 mm
Front Right	195/60 R15	88H	Annaite	AN600	V	0524	0 mm
Rear Left	185/65 R15	88H	Bridgestone	B250	V	4016	0 mm
Rear Right	185/65 R15	92T	Dunlop	Sp-Sport	V	0322	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIR BAG	B1042	ECU SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.Excessive play on clutch pedal.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front and rear of vehicle.
Brakes: Front left speed sensor damaged.
Undercarriage: Engine splash plate missing.Vehicle undercarriage dirty
Road Test: Vehicle unsafe to drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



90 DEGREE RIGHT




DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



ENGINE 1



Front chassis



Brake and shock absorber repor

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Rear chassis


Diagnostic report


Aircon condenser


Front left brake caliper dust


Spare wheel Accessories


Right quarter window

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Front bumper stiffener



Oil cap and dipstick



Manual Transmission



Bonnet release handle



Dipstick



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Tailgate



Rear bumper



Rear bumper



Load Body



Load Body



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026




Rim Rear Left




Bolt(s) / Nut(s) Rear Wheel Left



Rim Front Left



Door Front Left



Front Fender Left



Side Mirror Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Seat Front Left



Rear Fender Right



Steering Wheel Trim



Sun Visor Right



Central Air Vent



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Carpet Front



Door Front Right



Side Mirror Right



Front Fender Right



Tyre Rear Right



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Roof



Bonnet



Grill



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214


DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Windscreen




Parking Brake Performance




Water level



Engine Wiring



Main Beam Right



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Engine Wiring



Headlight Right



Headlight Left



Air cleaner



Engine Wiring



Shock Absorber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT


Report No:
2017316486
DATE
23/10/2026



Bolt(s) / Nut(s) Front Wheel Right



Rim Front Right



Front Fender Right / Inner Tray



Engine Wiring



Wheel bearing Front Left



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Sill Panel Left



Sill Panel Right



Sill Panel Right



Gearbox



CV Joint(s) Boot(s) Front Left (inner/outer)



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026




Tyre Front Right



Tyre Front Left



Engine Wiring



Engine Wiring



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Radiator Cradle



Speed Sensor



Ball Joint(s) Front Axle Right



Chassis



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Chassis



Mounting Rubber(s) Rear Axle Right



Rear Axle



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Rim Rear Left



Load Body



Fuel Tank



Main Beam Left



Steering Rack Boot Left



Steering Rack Boot Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Belly plates



Tail Light Left



Radio/CD/USB



Air Conditioner



Hood Lining



Mirror Adjusters

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214

DEKRA

CONDITION REPORT

Report No:
2017316486
DATE
23/10/2026



Door Lock Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADNUSN1D5U0210214