DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	FPW825L
Model	FORTUNER 2.4 GD-6 RB DSL AT [2020-2022]	Register Number	
VIN	AHTCB3GS002015735	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model	2021	Paint Finish	TWO COAT UNI
Km Reading	156,661 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Radio/CD/USB Defective	Repair
Sun Visor Right Loose / Excessive Play	Repair
Hood Lining Dirty	Repair
Door Panel Front Right Damaged	Repair
Door Sealing Rubber Front Right Damaged	Replace
Door Lock Boot Lid Malfunction	Replace
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Grill Damaged	Repair
Bonnet Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Rear Left Worn	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Chassis Damaged	Repair
Gearbox Oil Sweat	Repair
Engine Noise Excessive	Repair
Jack Missing	Replace
Vehicle license disk missing	Replace
Front left and right tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.82	4.35	-	
Rear	3.55	4.01	-	
Emergency / Parking	0.18	2.13	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/70 R17	121S	Bfgoodrich	All-Therrian	V	4718	5 mm
Front Right	265/65 R17	112S	Bridgestone	Dueler	V	2921	4 mm
Rear Left	265/65 R17	112S	Dunlop	Grandtrek	V	2321	0 mm
Rear Right	265/65 R17	112S	Bridgestone	Dueler	V	3519	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS AIRBAG	B1826	SIDE SQUIB(LEFT) CIRCUIT OPEN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.Interior boot lid handle missing.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Tyres and Rims: Only loose rim inside of vehicle.
Undercarriage: Bottom of engine covered.
Road Test: Gear selection faulty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER




Automatic Transmission



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



ENGINE 1



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare rim and Accessories


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735


DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



90 DEGREE RIGHT



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Sun Visor Right



Door Panel Front Right



Steering Wheel Trim



Hood Lining



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Rear bumper




Rear Fender Right



Rear Fender Right



Door Sealing Rubber Front Right



Front Fender Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Front Bumper



Front Bumper



Front Bumper



Grill



Radio/CD/USB



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Side Mirror Left



Front Fender Left



Sill Panel Left



Sill Panel Left



Bolt(s) / Nut(s) Rear Wheel Left



Gearbox


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Engine



Tyre Rear Left



Chassis



Roof



Boot Lid / Hatch door



Boot Lid / Hatch Door Rubbers

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735

DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Door Lock Boot Lid



Bonnet



Water level



Windscreen



Windscreen



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735


DEKRA

CONDITION REPORT

Report No:
2017317486
DATE
26/10/2026



Door Front Right



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTCB3GS002015735