DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	JD37PLGP
Model	COROLLA QUEST 1.6 PLUS [2016-2021]	Register Number	
VIN	AHTLB52E103141531	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/09/2026
Color	BLUE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT METALLIC
Km Reading	268,172 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Central Air Vent Damaged	Replace
Switch Electrical Window Winder front left Damaged	Replace
Windscreen Wiper Damaged	Replace
Tail Light Right Scratched	Repair
Headlight Left Defective	Repair
Headlight Right Scratched	Repair
Seat Front Left Damaged	Repair
Seat Rear Damaged	Repair
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Boot Carpet Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Dented	Repair
A • Pillar Right Dented	Repair
B • Pillar Left Dented	Repair
B • Pillar Right Dented	Repair
C • Pillar Left Residual Traces of Repair	Repair
C • Pillar Right Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Damaged	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Replace
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Roof Dented	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Rear Left Leak	Replace
Shock Absorber Rear Right Leak	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Main Beam Left Damaged	Repair
Chassis Dented	Repair
Cross Member Rear Left Dented	Repair
Cross Member Rear Right Damaged	Repair
Gearbox Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Jack Missing	Replace
Front right shock absorber weak	Replace
Deceleration parking brake defective	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026

Damage	Repair Way
Engine oil sump damaged	Replace
Front and rear tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.24	3.2	-	
Rear	2.15	2.66	-	
Emergency / Parking	1.49	0.14	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/60 R15	88H	Annaite	AN600	V	0124	4 mm
Front Right	195/60 R15	88H	Annaite	AN600	V	0125	4 mm
Rear Left	185/65 R15	88H	Continental	Contipremuim	V	1023	1 mm
Rear Right	185/65 R15	92T	Barum	Brillantis	V	1519	1 mm
Spare	185/65 R15	92T	Barum	Brillantis	V	1919	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Lights: Front left headlight lens faded
Interior: Vehicle interior dirty and panels scratched.Boot release handle not opening.Gear knob faded.
Body • Exterior: Signs hail damage on body panels.Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to rear of vehicle.
Tyres and Rims: Spare wheel lock down pin missing.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



90 DEGREE RIGHT



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



ENGINE 1



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Front chassis



Rear chassis




Engine oil sump



LF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT


Report No:
2017317467
DATE
26/10/2026




RF TYRE TREAD



Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Central Air Vent



Central Air Vent



Front Fender Right



Side Mirror Right



Rim Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Door Rear Right



Rear Fender Right



Seat Rear



Door Sealing Rubber Rear Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Rear bumper



Boot Lid / Hatch door



Roof



Tail Light Right



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



C • Pillar Left



Seat Rear



Door Sealing Rubber Rear Left



Seat Front Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Side Mirror Left




Bonnet



Steering Wheel Trim



Boot Carpet



Parking Brake Performance



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Headlight Left



Water level



Control Arm Bush(es) Front Axle Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Control Arm Bush(es) Front Axle Left



Sill Panel Left



Rim Rear Left



Shock Absorber Rear Left



Shock Absorber Rear Right



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Engine



Stabilizer Mounting Front Right



Stabilizer Mounting Front Left



Chassis



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Cross Member Rear Right



Inner Boot Floor Pan and Spare Wheel Well



Cross Member Rear Left



CV Joint(s) Boot(s) Front Left (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)



Main Beam Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



Water level



Windscreen Wiper



Switch Electrical Window Winder front left



A • Pillar Right



B • Pillar Right



C • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531

DEKRA

CONDITION REPORT

Report No:
2017317467
DATE
26/10/2026



B • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTLB52E103141531