CONDITION REPORT

Report No: 2017315065
DATE 21/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	21/10/2026		
Inspection Date	21/10/2026		

Vehicle Data

Vehicle Type	MINI BUS	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	JX61GWGP
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2020-2022]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P007119444	Last COR	
Engine Number		License Expiry Date	28/02/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2021	Fuel	DIESEL
Km Reading	523,015 KM	Transmission	MANUAL
Cab / Body Type	OTHERS		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Caps Defective	Replace
Windscreen Wiper Worn	Replace
Tail Light Left Cracked	Replace
Tail Light Right Cracked	Replace
Headlight Left Broken	Replace
Headlight Right Defective	Replace
Seat Front Left Worn	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Excessive Wear & Tear	Repair
Seat Rear (2. Row) Excessive Wear & Tear	Repair
Door Panel Front Left Damaged	Repair
Door Panel Rear Left Missing	Replace
Door Sealing Rubber Rear Left Excessive Wear & Tear	Replace
Door Lock Front Left Damaged	Repair
Door Lock Front Right Damaged	Repair
Door Lock Boot Lid Damaged	Repair
Dash Padding Defective	Repair
Window Winder front left Missing	Replace
Window Winder front right Missing	Replace
Boot Panel Left Damaged	Repair
Gear Lever Dust Boot Torn / Cut	Replace
Clutch Pedal Rubber Missing	Replace
Brake Pedal Rubber Worn	Replace
Side Mirror Left Damaged	Repair
Front Bumper Cracked	Replace
Grill Broken	Repair
Bonnet Dented	Repair
A • Pillar Left Residual Traces of Repair	Repair
B • Pillar Right Dented	Repair
C • Pillar Left Defective	Repair
C • Pillar Right Defective	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Rear Fender Left / Inner Tray Paintwork • Scratched	Repair
Rear Fender Right / Inner Tray Defective	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Sealing / Rubber Front Door Left Excessive Wear & Tear	Replace
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Fuel Flap Corrosion	Repair
Sill Panel Left Residual Traces of Repair	Repair
Sill Panel Right Damaged	Repair
Rocker Panel Right Dented	Repair
Sliding Door Damaged	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Caliper 1. Axle left Defective	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026

Damage	Repair Way
Steering Rack Defective	Repair
Rebound Rubber Front Axle Left Cracked	Replace
Rebound Rubber Front Axle Right Cracked	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Damaged	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Right Smooth	Replace
Gearbox Oil Sweat	Repair
Differential Oil Sweat	Repair
Fuel Tank Damaged	Replace
Radiator Cradle Damaged	Repair
Engine Smoke Excessive	Repair
Body Exterior	Residual traces poor repair on body panels
Body Exterior	Dents scratches stone chips on body panels
Front left plastic trim	Damaged
Rear door lock	Damaged

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	5.3	4.2	-	
Rear	1.0	0.2	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15C	106/104R	Anchee	Ac838	V	4625	3 mm
Front Right	195R15LT	106/104Q	Linglong	LMC7	V	4825	1 mm
Rear Left	195R15C	106/104R 8PR	FIREMAX	Radial 913fm	V	1424	3 mm
Rear Right	195R15LT	106/104Q 8PR	LINGLONG	LMC7	V	4625	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENGINE	P0400	EXHAUST GAS RECIRCULATION (EGR) FLOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Abs light illuminated Engine light illuminated Airbag light illuminated
Lights: Head lights both loose
Interior: Boot lid inner cover/panels missingRight rear inner panels defective Right front inner panel defective Left rear inner panel defective Residual traces of poor repairs on Left inner body panelDoors mechanism defective (doesn't lock)Rear Left window mechanism faulty (not closing)
Body • Exterior: Grill loose bolts missing needs to be fastened Tow Bar mounting bracket bolts missing
Brakes: Front left Caliper missing bolt
Tyres and Rims: Sparewheel Missing
Loose Items (Jack, Wheel Spanner, etc.): Jack and Wheel Spanner missing

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



INTERIOR (FRONT DRIVER DOOR)


Manual


FRONT RIGHT CORNER



90 DEGREE FRONT


90 DEGREE LEFT


REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026




90 DEGREE RIGHT



90 DEGREE REAR




DASHBOARD (W/ ENGINE RUNNING)



Lights illuminated



ODOMETER



Diagnostics


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Brake report



Boot lid inner panel cover



Rear inner panel



Rear inner body panel



Front right inner panel



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444


DEKRA

CONDITION REPORT


Report No:
2017315065
DATE
21/10/2026




Tow bar mounting




Oil cap and dipstick



Rear Chasis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Water level



Grill



Grill



Grill



Grill



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Bonnet



Bonnet



Headlight Right



Headlight Right



Headlight Left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Front Bumper



Front Fender Right



Rear Fender Left



Front Fender Left



Rear Fender Right



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Door Rear Left



Door Rear Left



Door Rear Left



Door Rear Left



Boot Lid / Hatch door



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Sill Panel Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Boot Panel Left



Tail Light Left



Tail Light Right



Side Mirror Left



Door Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444


DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Door Front Right



Door Front Right



A • Pillar Left



Front Fender Right / Inner Tray



Front Fender Right / Inner Tray



Front Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



A • Pillar Left



A • Pillar Left



Rear Fender Left / Inner Tray



Rear Fender Left / Inner Tray



Sealing / Rubber Front Door Left



Sealing / Rubber Front Door Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Fuel Flap



Windscreen



Windscreen



Door Panel Front Left



Door Panel Front Left



Door Panel Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Window Winder front left



Window Winder front left



Gear Lever Dust Boot



Clutch Pedal Rubber



Brake Pedal Rubber



Dash Padding

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444


DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Dash Padding



Seat Front Left



Seat Front Left



Seat Front Right



Seat Front Right



Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Window Winder front right



Rear Fender Right



Rocker Panel Right



Rear bumper



B • Pillar Right



B • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Seat Rear



Seat Rear (2. Row)



Seat Rear (2. Row)



Seat Rear (2. Row)



Door Sealing Rubber Rear Left



Door Panel Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Windscreen Wiper



Windscreen Wiper




Tyre Front Right



Tyre Rear Right



Gearbox



Control Arm Bush(es) Front Axle Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right



Differential



Fuel Tank

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Fuel Tank



Steering Rack




Steering Rack



Caliper 1. Axle left



Rebound Rubber Front Axle Right



Rebound Rubber Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Rear Fender Right / Inner Tray



Engine



Radiator Cradle



Sill Panel Left



Sill Panel Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



C • Pillar Left



C • Pillar Right



Roof



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT


Report No:
2017315065
DATE
21/10/2026



Roof



Roof



Roof



Roof



Caps



Door Lock Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444

DEKRA

CONDITION REPORT

Report No:
2017315065
DATE
21/10/2026



Door Lock Front Right



Door Lock Boot Lid



Sliding Door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P007119444