DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	05/10/2026		
Inspection Date	05/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	NONE
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P207149447	Last COR	
Engine Number		License Expiry Date	30/06/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2023	Fuel	DIESEL
Km Reading	356,546 KM	Transmission	MANUAL
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026





Damage	Repair Way
Engine Wiring Defective	Repair
Fan Belt Damaged	Replace
Under bonnet insulation cover Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Damaged	Replace
Tail Light Left Defective	Repair
Tail Light Right Defective	Repair
Headlight Left Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Hood Lining Defective	Repair
Door Panel Rear Left Defective	Repair
Door Handle Rear Left Damaged	Replace
Door Sealing Rubber Rear Left Missing	Replace
Door Lock Front Left Damaged	Replace
Door Lock Boot Lid Damaged	Replace
Carpet Rear Damaged	Repair
Steering Wheel Trim Damaged	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Paintwork • Scratched	Repair
Front Fender Right / Inner Tray Paintwork • Scratched	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Rear Fender Right / Inner Tray Damaged	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Damaged	Repair
Weather Strip Door Front Right Damaged	Replace
Boot Lid / Hatch door Damaged	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Window Front Door Left Defective	Repair
Caliper 1. Axle left Damaged	Replace
Caliper 1. Axle right Damaged	Replace
Brake Drum 2. Axle left Defective	Repair
Speed Sensor Damaged	Replace
Brake Piping Defective	Replace
Parking Brake Performance Insufficient	Repair
Brake fluid level Insufficient	Replace
Steering Rack Defective	Replace
Axle Mounting Rear Right Damaged	Repair
Spring Rear Left Defective	Repair
Spring Rear Right Defective	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm(s) Front Axle Left Defective	Repair
Control Arm(s) Front Axle Right Damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026

Damage	Repair Way
Mounting Rubber(s) Rear Axle Left Loose / Excessive Play	Repair
Tyre Front Left Damaged	Replace
Tyre Front Right Worn	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Sub Frame Damaged	Repair
Catalytic converter Missing	Replace
Gearbox Mountings Cracked	Replace
Gearbox Oil Leak	Repair
Fuel Tank Dented	Repair
Center Prop Shaft Bearing(s) Damaged	Replace
Radiator Cradle Damaged	Repair
Brakes Insufficient	Repair
Gear Selections Malfunction	Repair
Differential Noise Excessive	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Warning lights illuminated on dashboard	Repair
Front and rear shock absorbers weak	Replace
Spare wheel missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.27	3.52	-	
Rear	1.14	1.06	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15C	106R	Powertrac	Vanmarch	V	4125	0 mm
Front Right	195R15C	106R	Powertrac	Vanmarch	V	1026	0 mm
Rear Left	195R15C	106R	Zextour	Highlander	V	0626	3 mm
Rear Right	195R15C	106R	Powertrac	Vanmarch	V	1026	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Signs of repair work done to engine.
Interior: Vehicle interior in poor condition.Rear left window net missing.Rear left door step box loose.
Body • Exterior: Rear left door does not open.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Boot does not open.
Steering: Steering rack leak.
Axle and Suspension: Some bolts missing on rear leaf springs
Undercarriage: Signs of repair work done to gearbox.
Road Test: Gearbox faulty.Vehicle unsafe to drive.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447


DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Brake and shock absorber repor



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447


DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Triangle



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Hood Lining



Hood Lining




Steering Wheel Trim



Seat Front Right



Front Fender Right / Inner Tray



Weather Strip Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Door Front Right



Door Front Right



Rear Fender Right



Rear Fender Right



Boot Lid / Hatch door



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Tail Light Left



Rear Fender Left



Door Rear Left


Door Rear Left



Door Front Left


Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Front Fender Left



Headlight Left



Bonnet



Bonnet



Windscreen



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Front Bumper



Front Bumper




Side Mirror Right



Windscreen Wiper



Roof



Parking Brake Performance

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Window Front Door Left



Front Fender Left / Inner Tray



Seat Front Left



Door Sealing Rubber Rear Left



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Seat Rear




Seat Rear (2. Row)



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray



Boot Lid / Hatch Door Rubbers



Carpet Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Door Panel Rear Left


Door Handle Rear Left


Under bonnet insulation cover


Water level


Brake fluid level


Rear Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Sill Panel Right



Sill Panel Right



Spring Rear Right



Bolt(s) / Nut(s) Rear Wheel Left



Rear Fender Left / Inner Tray



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Sill Panel Left




Sub Frame



Control Arm(s) Front Axle Right



Fan Belt



Steering Rack



Stabilizer Mounting Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Tyre Front Right



Tyre Front Left



Fuel Tank



Gearbox



Gearbox Mountings



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Catalytic converter



Caliper 1. Axle left



Caliper 1. Axle right



Engine Wiring



Front Bumper



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Radiator Cradle



Engine Wiring



Control Arm(s) Front Axle Left



Spring Rear Right



Brake Drum 2. Axle left



Speed Sensor

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Parking Brake Performance



Parking Brake Performance



Mounting Rubber(s) Rear Axle Left



Brake Piping



Center Prop Shaft Bearing(s)



Axle Mounting Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447

DEKRA

CONDITION REPORT

Report No:
2017307483
DATE
05/10/2026



Spring Rear Left



Water level



Door Lock Front Left



Door Lock Boot Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P207149447