DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	LT40HSGP
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P407152432	Last COR	
Engine Number		License Expiry Date	
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2023	Fuel	DIESEL
Km Reading	311,718 KM	Transmission	MANUAL
Cab / Body Type	OTHERS		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Radio/CD/USB Missing	Replace
Seat Front Right Damaged	Repair
Seat Rear (2. Row) Damaged	Repair
Door Panel Front Right Damaged	Repair
Side Mirror Right Cracked	Repair
Bonnet Paintwork • Flaking	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Sill Panel Right Dented	Repair
Sliding Door Paintwork • Scratched	Repair
Window Rear Door Right Cracked	Replace
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Parking Brake Performance Malfunction	Repair
Tyre Front Left Damaged	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Defective	Replace
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Signs of spray work done on some body panels
Vehicle struggle to start	Repair
Engine management lights illuminated	Repair
All four tires deferred name brand and sizes	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	3.0	-	
Rear	0.7	3.9	-	
Emergency / Parking	0	0	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195R15	106/104R	Dunlop	Sp 175	V	2516	0 mm
Front Right	195/70R15	104/102R	Double king	Dk768	V	0825	2 mm
Rear Left	195R15	106/104S	Toyo	Ho7	V	2023	0 mm
Rear Right	195R15	106/104R	Double king	Dk256	V	1424	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	P0607	CONTROL MODULE PERFORMANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



Shock and brake report



Diagnostic report



No spare wheel



Coolant bottle



Oil cap and dipstick



Manual

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026




90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432


DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



Parking Brake Performance



Service Brake Performance Rear Axle



Seat Front Right



Door Panel Front Right



Side Mirror Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



Water level



Radio/CD/USB



Seat Rear (2. Row)



Window Rear Door Right



Sliding Door



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



Door Front Left



Door Front Right



Rear Fender Right



Boot Lid / Hatch door



Sill Panel Right



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432

DEKRA

CONDITION REPORT

Report No:
2017309124
DATE
09/10/2026



Tyre Rear Left



Tyre Front Left



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P407152432