Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RXRU015818

Odometer Reading: 52546
License Plate: LV34THGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	2
09 - Electronic central electric	0
15 - Airbag	2
17 - Instrument cluster	0
19 - Gateway	1
25 - Immobilizer	0
44 - Power steering	0
56 - Radio	0

DTC (6)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1504:00/05 380:000	Air intake system Leak detected	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U101F00	Engine control module (ECM) ,Read out DTC	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

Technician Notes
2017317553

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.