

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZLU006847

Odometer Reading: 260870km
License Plate: KJY392MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 3
03 - Brakes 1	 3
09 - Electronic central electric	 4
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 1
25 - Immobilizer	 1
44 - Power steering	 0
56 - Radio	 2

DTC (15)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
P0130:00/00 304:000	O2 Sensor Circ.,Bank1-Sensor1 Malfunction	Passive/Sporadic
P1918:00/06 424:000	Load signal terminal DF of Generator Open circuit/short circuit to B+	Active/static
P0300:00/00 768:000	Random/Multiple Cylinder Misfire Detected	Active/static

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
C101A07	Left front ABS Wheel Speed Sensor (WSS) Mechanical fault	Passive/Sporadic

C101A29	Left front Wheel Speed Sensor (WSS) Range/performance	Passive/Sporadic
---------	--	------------------

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
00975:011	Rear window defogger - Open circuit	Active/static
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01117:008	Load signal for alternator terminal DF - Implausible signal	Passive/Sporadic
03591:011	Signal horn activation - Open circuit	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
00625:004	Speed signal - No signal/communication	Passive/Sporadic
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes
2017309195

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.