

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZLU014830

Odometer Reading: 143477
License Plate: JN18HBGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 1
03 - Brakes 1	 2
09 - Electronic central electric	 4
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 1
25 - Immobilizer	 2
44 - Power steering	 1
56 - Radio	 0

DTC (12)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1504:00/05 380:000	Air intake system Leak detected	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U101F00	Engine control module (ECM) Read out DTC	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
03429:011	Activation of right cornering light - Open circuit	Active/static
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00975:012	Rear window defogger - Electrical error in circuit	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes
2017302938

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.