**Shop Name:** –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261020120658
Test Time: 2026-10-20 12:06:58
Technician: Sbu

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZMU008980

Odometer Reading: 122519
License Plate: KHZ221MP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 9 )

| System | Status/DTC |
|---|---|
| 01 - Engine Control Module 1 | 0 |
| 03 - Brakes 1 | 0 |
| 09 - Electronic central electric | 1 |
| 15 - Airbag | 0 |
| 17 - Instrument cluster | 0 |
| 19 - Gateway | 0 |
| 25 - Immobilizer | 0 |
| 44 - Power steering | 0 |
| 56 - Radio | 1 |

## DTC ( 2 )

### 09 - Electronic central electric ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 01758:011 | Lamps for brake lights - Open circuit | Active/static |

### 56 - Radio ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 01044:000 | Control module incorrectly coded | Passive/Sporadic |

## Technician Notes

2017314605

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*