Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20260721132611
Test Time: 2026-07-21 13:26:11
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU001861

Odometer Reading: 86115
License Plate: KG78MJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V24.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	0
09 - Electronic central electric	0
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	1
44 - Power steering	0
56 - Radio	1

DTC (3)

15 - Airbag (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2017273322

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.