Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU018826

Odometer Reading: 230089
License Plate: KX87FSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	2
04 - Steering Angle Sender	0
09 - Electronic central electric	0
15 - Airbag	4
17 - Instrument cluster	0
19 - Gateway	1
25 - Immobilizer	1
44 - Power steering	0
56 - Radio	1

DTC (9)

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

15 - Airbag (4 DTCs)

DTC	Description	Status
B200600	Control module does not match vehicle	Passive/Sporadic
B101600	Front passenger airbag off indicator	Passive/Sporadic
B10021B	Front passenger airbag igniter ,Resistance too high	Active/static
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2017326886

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.