

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU019248

Odometer Reading: 61044
License Plate: LPL238MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 2
04 - Steering Angle Sender	 0
09 - Electronic central electric	 4
15 - Airbag	 2
17 - Instrument cluster	 2
19 - Gateway	 2
25 - Immobilizer	 0
44 - Power steering	 0
56 - Radio	 0
61 - Battery Regulation	 0

DTC (12)

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
00967:007	Left flashers - Short circuit to ground	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

01598:000

Drive battery voltage

Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
B103E1B	Fuel level sensor 1 Resistance too high	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

Technician Notes
2017294612

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.